



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : HSBC LIFE (SINGAPORE) PTE LTD

11/5/2023

Survey Details:

| | |
|---------------------|--|
| Date of loss | 22-Mar-23 |
| Date of appointment | 4-Apr-23 |
| Date of survey | 5-Apr-23 |
| Location of survey | HUA CHIN (2000) TRADING MOTOR SVC CENTRE |

Vehicle Details:

| | |
|----------------------|-------------------|
| Claim Type: | Third Party Claim |
| Vehicle number | CDQ 8371 |
| Make and Model | YAMAHA |
| Date of registration | |
| Excess | |
| Market Value | |
| Parf Rebate | |
| Nett Loss | |

Repair details:

| | |
|------------------|------|
| Initial Estimate | \$ - |
|------------------|------|

Proposed/Revised repair cost:

| | |
|--------------------------------|------|
| Parts | |
| Check items (estimate) | |
| Labour | |
| Total | \$ - |
| Lump Sum(if applicable) | |

| | |
|----------------------------------|----------|
| Number of days for repair | <u>5</u> |
|----------------------------------|----------|



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

No GIA Report provided. The estimate repair cost of the damaged vehicle is in the region of \$3,000.00 - \$4,000.00.

Mandate:

| Liability(TP) | % | |
|-----------------------|----------------|-------------|
| Proposed repair cost | \$ | |
| Loss of use | \$ | no. of days |
| Loss of rental | \$ | no. of days |
| Loss of income | \$ | no. of days |
| LTA search fees | \$ | |
| Others | \$ | |
| Proposed Total | #VALUE! | |