

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 22/03/23
 VEHICLE NO: PA6309B
 DRIVER: LOW KIA PANG
 ATTENTION TO:
 PREPARED BY: Mustapa Bin Awang

LOCATION: Gul Workshop
 Q REF No: Q23/03/1407
 DEPARTMENT: WTS Bus Department
 ACCIDENT DATE: 22/03/23
 REF No: JW/0323/172

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	TYRE RIM	1	210	226.80
2	TYRE	1	280	302.40
3	SIKAFLEX	6	22	142.56
Labour Costs				
1	TO REMOVE & RENEW L/H/R OUTER TYRE & RIM	1	80	86.40
2	TO INSTALL LIVERY ON L/H SIDE BODY PANEL	1	792	855.36
3	TO REPAIR & ALIGN WHEEL ALIGNMENT	1	120	129.60
4	TO REMOVE & INSTALL SIDE MIRROR WINDOW GLASS 3 PCS WITH SEALANT & RUBBER SEAL.	1	600	648.00
5	TO REMOVE & INSTALL L/H SIDE ALL PASSENGER SEAT, TO FACILITATE REPAIR WORK.	1	500	540.00
6	TO REMOVE & INSTALL L/H SIDE PANEL TO FACILITATE REPAIR WORK	1	400	432.00
7	TO PANEL BEAT, CUTTING FABRICATE & WELDING SIDE PANEL, TO FLATTEN & SMOOTHEN BODY PANEL FOR INSTALLING LIVERY STICKER	1	3000	3,240.00
TOTAL:				6,603.12
Total Amount				SGD 6,603.12

Remarks:
 LOU 12 DAYS

Mustapa 31/3/23

Signature of Workshop Dpt

Thomas

Signature of Department Head

Mustapa

31/3/2023

Signature of Claim Department