

ASS. REC. BY:

REF:

AIS / 230035161kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) \$ - RS. SI

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ESTIMATE

NO : QUOT202304-000003(00)
DATE : 04/04/2023
POLICY NO : SP2003907937
VEH REG NO : SMS7156J
MAKE/MODEL : MERCEDES BENZ GLA180
PROGRESSIVE
CHASSIS NO : W1N2477842J376497
ENGINE NO : 28291480792942
REG. DATE : 2022

ATTN : MOTOR CLAIMS DEPT

TEL :

FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 24/03/2023

Not Notified
Mercury B & Paim
Ex TBA
18 days

Estimate Repair Cost to Vehicle No : SMS7156J

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Rear windscreen	1	Bro 650.00	650.00 ✓
2 Tailgate	1	Ry 1,350.00	1,350.00 ✓
3 Tailgate centre logo	1	na 42.00	42.00 ✓
4 Tailgate "GLA180" emblem	1	na 68.00	68.00 ✓
5 Tailgate weatherstrip	1	dit na 210.00	210.00 ✓
6 Tailgate absorber - RH / LH	2	420.00	840.00 ?
7 Tailgate stopper - LH	1	su 16.00	16.00 X
8 Tailgate speaker trimboard	1	Bu 198.00	198.00 ✓
9 Tailgate wiper arm	1	su 78.00	78.00 X
10 Tailgate wiper blade	1	su 32.00	32.00 X
11 Tailgate inner trimboard	1	Bu 128.00	128.00 ✓
12 Tailgate inner trimboard clips	12	na 6.50	78.00 ✓
13 Tailgate handle trimboard	1	85.00	85.00 ?
14 Tailgate handle trimboard clips	8	6.50	52.00 ?
15 Tailgate outer trim - LH	1	nd / na 112.00	112.00 ✓
16 Tailgate reflector - LH	1	Bro 268.00	268.00 ✓
17 Rear end panel	1	Ry 750.00	750.00 ✓
18 Rear end panel top garnish	1	78.00	78.00 ?
19 Rear end panel top garnish clips	8	6.50	52.00 ?
20 Rear floorboard panel	1	na 680.00	680.00 X
21 Rear floorboard top cover	1	225.00	225.00 ?
22 Rear fender - LH	1	Ry 1,680.00	1,680.00 ✓
23 Rear fender inner trim - LH	1	Return 360.00	360.00 ✓
24 Rear fender inner shield - LH	1	CM 115.00	115.00 ✓
25 Rear fender inner shield clips - LH	20	na 5.50	110.00 ✓
26 Rear fender air duct - LH	1	CM 56.00	56.00 ✓
27 Rear fender sub panel - LH	1	580.00	580.00 ?
28 Rear petrol flap	1	118.00	118.00 ?
29 Rear petrol cover	1	mi 95.00	95.00 ✓
30 Rear petrol cover push button	1	50.00	50.00 ?
31 Rear wheel arch garnish - LH	1	Ry 110.00	110.00 ✓
32 Taillamp assy - LH	1	Ro 480.00	480.00 ✓
33 Taillamp panel - LH	1	Ry 178.00	178.00 ✓



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 24/03/2023

ESTIMATE

NO : QUOT202304-000003(00)

DATE : 04/04/2023

POLICY NO : SP2003907937

VEH REG NO : SMS7156J

MAKE/MODEL : MERCEDES BENZ GLA180
PROGRESSIVE

CHASSIS NO : W1N2477842J376497

ENGINE NO : 28291480792942

REG. DATE : 2022

Estimate Repair Cost to Vehicle No : SMS7156J

Description	Quantity	Unit Price	Amount
		S\$	S\$
34 Taillamp lower bracket - LH	1	CM 38.00	38.00 ✓
35 Rear bumper - upper	1	B 780.00	780.00 ✓
36 Rear bumper - lower	1	B/L 260.00	260.00 ✓
37 Rear bumper reinforcement	1	B 350.00	350.00 ✓
38 Rear bumper top chrome	1	me 228.00	228.00 ✓
39 Rear bumper inner frame	1		95.00 ?
40 Rear bumper lower chrome	1	CM 112.00	112.00 ✓
41 Rear bumper side retainer - LH	1	CM 65.00	65.00 ✓
42 Rear bumper lower bracket - centre	1		68.00 ?
43 Rear bumper lower bracket - RH / LH	1		24.00 ?
44 Rear bumper switch module	1		155.00 ?
45 Rear bumper switch module wire	1		135.00 ?
46 Rear bumper reverse sensor	2	8 135.00	810.00 ?
47 Rear bumper reverse sensor seals	6		8.00 48.00 ?
48 Rear bumper sensor cable	1		108.00 108.00 ?
49 Rear bumper clips	15		6.50 97.50 ✓
50 Rear exhaust end chrome - LH	1		78.00 78.00 ✓
51 Rear exhaust end chrome bracket - LH	1		48.00 48.00 ✓
52 Rear exhaust heating seal	1		168.00 168.00 ✓
53 Rear shock absorber - LH	1		265.00 265.00 ?
54 Rear lower arm - LH	1		82.00 82.00 ?
55 Rear lower arm cover (top) - LH	1		28.00 28.00 ?
56 Rear lower arm cover (bottom) - LH	1		28.00 28.00 X
57 Rear training arm - LH	1		156.00 156.00 ?
58 Rear spring link - LH	1		165.00 165.00 ?
59 Rear spring link lower cover - LH	1		12.00 12.00 ?
60 Rear under cover - LH	1		78.00 78.00 X
61 Rear sport rim - LH	1		680.00 680.00 ✓
62 Steering air bag	1	Ar 1,480.00	1,480.00 ✓
63 knee air bag	1	" 780.00	780.00 ✓
64 Air bag control unit	1	me 480.00	480.00 ✓
65 Front safety belt - RH / LH	2	me 420.00	840.00 ✓
66 Front safety belt catch - RH / LH	2		160.00 320.00 ?
67 Rear safety belt - RH / LH	2	me 298.00	596.00 ✓



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 24/03/2023

ESTIMATE

NO : QUOT202304-000003(00)

DATE : 04/04/2023

POLICY NO : SP2003907937

VEH REG NO : SMS7156J

MAKE/MODEL : MERCEDES BENZ GLA180
PROGRESSIVE

CHASSIS NO : W1N2477842J376497

ENGINE NO : 28291480792942

REG. DATE : 2022

Estimate Repair Cost to Vehicle No : SMS7156J

Description	Quantity	Unit Price	Amount
		S\$	S\$
68 Rear safety belt - centre	1	255.00	255.00 ?
69 Rear safety belt catch - RH / LH	2	145.00	290.00 ✓
70 Front windscreen moulding - RH	1	85.00	85.00 ?
71 Front windscreen moulding clips - RH	6	12.00	72.00 ✓
72 Bonnet	1	980.00	980.00 ✓
73 Bonnet hinges - RH / LH	2	68.00	136.00 ✓
74 Bonnet absorber - RH / LH	2	75.00	150.00 X
75 Bonnet spring - RH	1	28.00	28.00 X
76 Bonnet lock - upper	1	92.00	92.00 X
77 Bonnet lock - lower	1	105.00	105.00 ?
78 Bonnet catch	1	55.00	55.00 X
79 Bonnet cable	1	52.00	52.00 ?
80 Support panel	1	480.00	480.00 ?
81 Support panel top garnish	1	88.00	88.00 ✓
82 Headlamp assy - RH	1	1,850.00	1,850.00 ✓
83 Headlamp control unit - RH	1	450.00	450.00 ?
84 Front grille	1	450.00	450.00 ✓
85 Front grille beam	1	198.00	198.00 ?
86 Front grille beam moulding - RH / LH	1	58.00	58.00 ✓
87 Front grille centre logo	1	95.00	95.00 ?
88 Front grille logo base	1	320.00	320.00 ?
89 Front grille inner support - top	1	178.00	178.00 ?
90 Front grille inner support garnish - top	1	86.00	86.00 ?
91 Front grille inner support - lower	1	165.00	165.00 ?
92 Front grille inner support cover - lower	1	68.00	68.00 ?
93 Front fender - RH	1	520.00	520.00 ✓
94 Front fender inner shield (front) - RH	1	128.00	128.00 ✓
95 Front fender inner shield clips - RH	20	5.50	110.00 ✓
96 Front fender rail - RH	1	24.00	24.00 ?
97 Front fender wheel arch garnish - RH	1	125.00	125.00 ✓
98 Front bumper	1	780.00	780.00 ✓
99 Front bumper reinforcement	1	350.00	350.00 ?
100 Front bumper reinforcement bracket - RH	1	125.00	125.00 ?
101 Front bumper lower member - centre	1	310.00	310.00 ?



TONG LUCK AUTO PTE LTD
 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722
 Tel: 6250 0088 Fax: 6250 5545
 Email: operation@tlauto.com.sg
 GST No: 201700521W UEN No: 201700521W

M/S : **ALLIANZ INSURANCE SINGAPORE PTE TLD**
 79, ROBINSON ROAD #09-01
 SINGAPORE 068897

PAGE: 4

ATTN : MOTOR CLAIMS DEPT
 TEL :
 FAX :
 YOUR REF NO :
 CLAIM TYPE : OWN DAMAGE
 ACCIDENT DATE : 24/03/2023

ESTIMATE

NO : QUOT202304-000003(00)
 DATE : 04/04/2023
 POLICY NO : SP2003907937
 VEH REG NO : SMS7156J
 MAKE/MODEL : MERCEDES BENZ GLA180
 CHASSIS NO : W1N2477842J376497
 ENGINE NO : 28291480792942
 REG. DATE : 2022

Estimate Repair Cost to Vehicle No : SMS7156J

Description	Quantity	Unit Price	Amount
		S\$	S\$
102 Front bumper lower member - RH	1	60.00	60.00
103 Front bumper sponge	1	118.00	118.00
104 Front bumper side retainer - RH / LH	2	12.00	24.00
105 Front bumper centre garnish	1	88.00	88.00
106 Front bumper fog lamp cover - RH	1	112.00	112.00
107 Front bumper centre grille	1	90.00	90.00
108 Front bumper lower chrome	1	228.00	228.00
109 Front bumper radar sensor	1	780.00	780.00
110 Front bumper towing cover	1	38.00	38.00
111 Front bumper sensor	2	138.00	276.00
112 Front bumper sensor seals	6	8.00	48.00
113 Front bumper sensor cable	1	152.00	152.00
114 Front bumper lower side garnish - RH	1	68.00	68.00
115 Front bumper under cover	1	175.00	175.00
116 Front bumper under cover - RH	1	36.00	36.00
117 Front bumper clips	15	6.50	97.50
118 Front number plate garnish	1	92.00	92.00
119 Air-con condenser	1	750.00	750.00
120 Radiator assy	1	850.00	850.00
121 Radiator top cover	1	75.00	75.00
122 Radiator lower cover	1	45.00	45.00
			33,180.00
		Add 10%	3,318.00
			36,498.00
SPECIAL NET			
123 Rear windscreen sealant	1	60.00	60.00
124 Tailgate " C&C" emblem	1	38.00	38.00
125 Rear tyre - LH	1	480.00	480.00
126 Rear number plate	1	40.00	40.00
127 Front number plate	1	40.00	40.00
128 Radiator coolant (tin)	2	60.00	120.00
			778.00
LABOUR			
129 To remove and refit rear windscreen	1	150.00	150.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79, ROBINSON ROAD #09-01
SINGAPORE 068897

PAGE: 5

ATTN : MOTOR CLAIMS DEPT
TEL :

FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 24/03/2023

ESTIMATE

NO : QUOT202304-000003(00)
DATE : 04/04/2023
POLICY NO : SP2003907937
VEH REG NO : SMS7156J
MAKE/MODEL : MERCEDES BENZ GLA180
PROGRESSIVE
CHASSIS NO : W1N2477842J376497
ENGINE NO : 28291480792942
REG. DATE : 2022

Estimate Repair Cost to Vehicle No : SMS7156J

Description	Quantity	Unit Price	Amount
		S\$	S\$
130 To remove and refit rear cushion seats, interior garnish and trimboard to facilitates the repairs	1	480.00	480.00 250
131 To transfer damaged tailgate interior mechanism to new tailgate	1	180.00	180.00 60
132 To remove and refit petrol tank to facilitates the repairs	1	280.00	280.00 80
133 To remove and refit air- con condenser, radiator and refill air-con gas	1	150.00	150.00 100
134 To remove and refit steering air bag, knee air bag, front & rear safety belt and air bag control unit	1	880.00	880.00 300
135 To remove and refit centre console box to enable to remove air bag control unit	1	180.00	180.00 100
136 To remove and refit rear bumper sensor	1	200.00	200.00 60
137 To check and rectify wiring system	1	120.00	120.00 40
138 To panel beat and straighten rear chassis frame, LH rear fender inner panel, RH front fender inner panel, RH front chassis frame, to cut and weld rear end panel, rear floorboard panel, LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	2,800.00	2,800.00 2200
139 To putty and spray paint on affected areas	1	2,800.00	2,800.00 1800
140 To reset and reprogram headlamp module and air bag control unit	1	680.00	680.00 250
			8,900.00

TOTAL S\$ 46,176.00

ADD GST @ 8% 3,694.08

GRAND TOTAL S\$ 49,870.08

SINGAPORE DOLLAR FORTY-NINE THOUSAND EIGHT HUNDRED SEVENTY AND CENTS EIGHT ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/03/2023 15:31 (SGT)
Reported by	Actual Driver
Date of Accident	24/03/2023 17:15 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMS7156J
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE LTD
Company Reg No	1XXXXX778Z
Email Address	too_tong.tan@mercedes-benz.com
Mobile Phone No	(Phone) +65-97302314
Alternative Phone No	(Office) +65-82821711

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Gla180
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1332

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2003907937

DRIVER

Name of Driver	MOHAMMED HARON BIN SAMAT
NRIC No	SXXXX204J
Date Of Birth	09/06/1957

IMPORTANT NOTICE

1. Please correctly report the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (Collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

FLASH ACCIDENT
REPORTING OFFICER

FRO BALAJI



Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

1900HRS 25 MARCH 2023

Sketch Plan

- A. SMS7156J
- B. JUT2250
- C. SH9839X
- D. JVQ1549

PIE TOWARDS
TUAS



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

778Z

SMS7156J

No

30 Apr 2023

MERCEDES BENZ

GLA180 PROGRESSIVE

Black

2022

28291480792942

W1N2477842J376497

96.0 kW (128 bhp)

\$32,239.00

25 Apr 2022

25 Apr 2022

0

\$37,135.00

Yes

24 Apr 2032

\$27,851.00

24 Apr 2032

A - Car up to 1600cc & 97kW (130bhp)

10

\$63,000.00

\$56,595.00

\$84,446.00

The information contained herein is correct as at 04 Apr 2023

OK