

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 23 Jun 2023

**Preliminary Advice**

Vehicle No	: SMS7156J	Accident Date	: 24/03/2023
Make	: MERCEDES-BENZ GLA180	Policy No.	: SP2003907937
Assignment Date	: 04/04/2023	Excess	: S\$700.00
Date of Inspection	: 05/04/2023	Est. Duration of Repair	: 18
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	51,558.90	(Estimate \$46,176.00 + Supplementary \$5,382.90)
Revised Amount	:S\$	37,913.20	
Check Items (Estimated)	:S\$	12,448.10	
Total	:S\$	50,361.30	

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	192,000.00
COE / PARF Rebate	:S\$	84,446.00
Salvage Value	:S\$	
Margin for Repair	:S\$	107,554.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.