Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Sharon Lim Date: 06 Apr 2023

Preliminary Advice

Vehicle No: SMS7156JAccident Date: 24/03/2023Make: MERCEDES-BENZ GLA180Policy No.: SP2003907937

Assignment Date : 04/04/2023 Excess : \$\$0.00 Date of Inspection : 05/04/2023 Est. Duration of Repair : 18

Inspection At : TONG LUCK AUTO PTE LTD (HQ)

160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY

SINGAPORE 575722

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,176.00
Revised Amount	:S\$	33,480.30
Check Items (Estimated)	:S\$	12,068.10
Total	:S\$	45,548.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 192,000.00

 COE / PARF Rebate
 :S\$ 84,446.00

Salvage Value :S\$

Margin for Repair :S\$ 107,554.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kir	ndly
	let us have your authorisation.	

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.