



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD
79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT
TEL : FAX :

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 24/03/2023

ESTIMATE

NO : QUOT202304-000003(00)
DATE : 20/06/2023
POLICY NO : SP2003907937
VEH REG NO : SMS7156J
MAKE/MODEL : MERCEDES BENZ GLA180
PROGRESSIVE
CHASSIS NO : W1N2477842J376497
ENGINE NO : 28291480792942
REG. DATE : 2022

Estimate Repair Cost to Vehicle No : SMS7156J

Description	Quantity	Unit Price S\$	Amount S\$
SUPPLEMENTARY PARTS			
1 Tailgate top trim	1	195.00	195.00
2 Tailgate top trim clips	6	6.50	39.00
3 Fuel filler door lock actuator	1	62.00	62.00
4 Taillamp seal - LH	1	26.00	26.00
5 Taillamp connecting wire - LH	1	150.00	150.00
6 Rear bumper reflector - LH	1	28.00	28.00
7 Rear upper control arm - LH	1	135.00	135.00
8 Rear knuckle arm - LH	1	950.00	950.00
9 Rear wheel hub bearing - LH	1	380.00	380.00
10 Rear torsion bar	1	185.00	185.00
11 Rear torsion bar link - LH	1	65.00	65.00
12 Rear sub frame	1	1,350.00	1,350.00
13 Rear sub frame rivet nut	2	9.00	18.00
14 Support panel mounting clips - RH / LH	2	28.00	56.00
			3,639.00
		Add 10%	363.90
			4,002.90
SPECIAL NET			
15 Rear triangle glass sealant - LH	1	40.00	40.00
			40.00
LABOUR			
16 To remove and refit LH rear triangle glass to facilitates the repairs	1	60.00	60.00
17 To remove and refit LH rear undercarriage and sub frame	1	600.00	600.00
18 To press in & out wheel hub bearing	1	180.00	180.00
19 To camber rear chassis frame	1	380.00	380.00
20 To computerise check wheel alignment	1	120.00	120.00
			1,340.00
TOTAL			S\$ 5,382.90
ADD GST @ 8%			430.63
GRAND TOTAL			S\$ 5,813.53

SINGAPORE DOLLAR FIVE THOUSAND EIGHT HUNDRED THIRTEEN AND CENTS FIFTY-THREE ONLY