SAS-LIV

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE:

03.04.2023

GBH5941K

INSURANCE: INCOME

MODEL:

Hyundai loniq

SURVEYOR: LKK-

VEHICLE NO.: SHB6616D

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UN	IT PRICE	A	MOUNT	
	Rear Bumper	1			\$	COLUMN TO SECURE OF THE PROPERTY OF THE PROPER	XR
	Rear Bumper Reinforcement	1			\$	394.80	?
	Rear Bumper Reinforcement Bracket RH/LH	2	\$	138.10	\$	276.20	?
	Rear Bumper Centre Moulding	1			\$	451.25	DEF
	Rear Bumper Clips	10	\$	2.20	\$		XNN
	Rear Bumper Reflector Lamp LH	1			\$	41.45	?
	Rear Bumper Tow Cover	1			\$	98.80	15cR
	Rear Bumper FogLamp	1			\$	201.50	rscr
	Rear Smart Key Antenna	1			\$	40.50	0
		·				10.00	,
	SUB TOTAL				\$	1,985.90	
	LESS 20%				\$	397.18	
	DISCOUNTED TOTAL				\$	1,588.72	
					Ť		
	Reverse Sensors	1			\$	180.00	not makin.
	Rear No.Plate With Trim Cover	1			\$	55.00	ICRA
					ľ		
					\$	235.00	
	LESS 10%				\$	23.50	1
	S/NETT TOTAL				\$	211.50	⊣
					Ť		1
	SPARE PARTS TOTAL				\$	1,800.22	1
					<u> </u>	.,000.22	1
	Labour Charge						
	Panel Beating				\$	400.00	350
	Spray Painting Charge				\$	300.00	
	Remove/Refix Reverse Sensor				\$	120.00	_
	TOTAL LABOUR				\$	820.00	
							_
	ESTIMATE TOTAL				\$	2,620.22	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKIC 314/2023 1555 2 DAY) CITECK ITEM PHOTO BATTER REPORTE PITOTO)