

Our Job Ref No : 305550435			ENGINEERING				
Date : 27.03.2023			ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969				
FIN	ALIZA	TION FORM					
То	To :LKK			Fax :			
Attn : NAZ							
Veh	icle Re	g No. : SHA44	47T		_	02.04.2023	
The	survey	and estimates of th	e repairs of the above-me	ntioned vehicle	are as follows	:-	
Z	The	repair job shall bill t	shall bill to:			SJJ8717S	
2.	The finalized amount shall be:						
	(a)	Spare Parts after			-		
	(b)	Labour Charges				The same of the sa	
		Total for Part-By	-Part Repair Cost				
	(c.)	Lumpsum Repair					
	- •	Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost				\$1,150.00	
	We shall treat the above amount as Correct and 7 working days Thank you for your assistance.			We confirm the estimates and finalized amount			
	Signat	ura t		Signature		NA2'LEK	
	Name	: CHIANG		_ Na			
	Tel	62148314	had a second	Da	1914/2023		
	101	: 65468156	Approximate the first of the second s		Allen Andrews		
	Fax						
1	Fax	-	Charles Control of the Control of th	. 0 . 1			
1	ficial (Jse Only em	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
r Of	ficial (Jse Only em	Amount	Attached		Remarks	
r Of	ficial U	Jse Only em te P/Day	Amount	Attached Yes or No		Remarks	
r Off	ficial U	Jse Only em te P/Day come Paid	Amount	Attached Yes or No YES N		Remarks	
Ren Loss Sun	It Ital Ra s of Indexey Fe	Jse Only em te P/Day come Paid es th Fee	Amount	Attached Yes or No YES		Remarks	
Ren Loss Sun LTA	It I	em te P/Day come Paid es		Attached Yes or No YES N		Remarks	

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SHS4447T

MAKE MODEL REG. 25.05.2017

DATE 02.04.2023 CHIANG/INCOME

TOYOTA PRILIS GA

Qty	Parts Description/ Labour Type Unit Price							
	and Scottiption, Labour	Турс	Office	Amount				
	1 REAR BUMPER		/ LRA	\$458.6				
	1 REAR BUMPER LOWER COVER		1 pet	\$552.6				
	1 REAR BUMPER REINFORCEMENT		SVC X?	\$318.8				
	1 REAR BUMPER UNDER SIDE COVERLH		XR	\$232.0				
	1 REAR BUMPER SIDE RETAINER LH/RH		such?	\$112.7				
1	0 REAR BUMPER CLIP		-NEC	\$22.0				
	SUB TOTAL			\$1,696.7				
	25.00%			\$424.:				
	DISCOUNTED TOTAL			\$1,272.				
			(A)6					
	1 REAR BUMPER MAT		X SUL	\$50.				
	1 BUMPER REVERSE SENSOR 10%		X 20C	\$135.				
				\$172.				
	Labour Charge							
	Panel Beating		350	\$600.				
	Spray Painting Charge		250	\$300.				
	Check Lighting		NNX	\$60.				
	Remove/Refix Reverse Sensor		30	\$60.				
	TOTAL LABOUR			\$1,020.				
	ESTIMATE TOTAL			\$2,464.				
				42,404.				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will							
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.							

NA2 LKIL 314/2023 1625 . 4/5 2 Days CHECK ITEM (1600) AFTER REPAIR PHOTO)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: