

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Ref:	CS3/CTI22006376/Kwp3m4-1	
	C/O KELVIN CHIA 1 HARBOURFRON KEPPEL BAY TOW		Date:	17/04/2023	
			Code:	CTI	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SDS 7228S	Veh. Inspected	SCL 813Y	
	Policy No.	DMPCSNW00196212100	Coverage (\$)	0.00	
	Claim No.	SS/AR/2023000043.CI(mpd)	Excess (\$)	0.00	
	Assign From	HAZDI (KC PARTNERSHIP)	Assign Date	04/04/2023	
2. Vehicle Particulars & Condition					
	Make & Model	BMW M6 (A)	c.c	4395	
	Engine No.	HIDDEN	Year of Reg.	2012	
	Chassis No.	WBSLZ92070C967409	Colour	METALLIC BLACK	
	Odometer	69725 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	265/35 ZR20	MICHELIN	4 mm	
	L/H Front Tyre	265/35 ZR20	MICHELIN	4 mm	
	R/H Rear Tyre	295/30 ZR20	MICHELIN	4 mm	
	L/H Rear Tyre	295/30 ZR20	MICHELIN	4 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	28/06/2022	Inspection Date	05/07/2022	
	Survey held at	THIAM HENG HUAT PTE LTD			
		176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				