

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts E	n Automo	bile CS3/CTI22006376/Kwp3-
	CHINA TAIPING IN	NSURANCE (S) PTE LTD		Ref:	C <del>33/CTI22000370/Kcy3</del>
	3 ANSON ROAD # SPRINGLEAF TO\	16-00 WERSINGAPORE 079909		Date:	05/07/2022 04/04/2023
				Code:	CTI
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SDS 7228S	Veh. Inspected	b	SCL 813Y
	Policy No.		Coverage (\$)		0.00
	Claim No.	SNM22D204567C02	Excess (\$)		0.00
	Assign From	HRENE TAY DI (KC PARTNERSHIP)	Assign Date		04/07/2022 04/04/2023
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.	Colour			
	Odometer	Steering			
	Brakes	Modification			
	General				
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	5. General Information				
	Accident Date	24/06/2022	Inspection Da	te	05/07/2022
	Survey held at	THIAM HENG HUAT PTE LTD			
		176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				