

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 05 Jun 2023

Preliminary Advice

Insured Vehicle No	: YN1919Z	Accident Date	: 01/04/2023
TP Vehicle No	: PC2674L	Assignment Date	: 05/04/2023
Make	: GOLDEN DRAGON XML6770J18	Est. Duration of Repair	: 7
Date of Inspection	: 05/04/2023		
Inspection At	: AUTO INSURE PTE LTD (HQ) 6 MARSILING LANE SINGAPORE 739145		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,022.72
Revised Amount	:S\$	9,912.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,912.56
 Lump Sum Repair	 :S\$	 7,900.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	4,451.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,549.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.