

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0326/2023/EQ
DATE : 31-Mar-23
WIP : 14104

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/4/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAY MONG SENG
ADDRESS : BLK 1 BILAL LANE
SINGAPORE 469075

TELEPHONE : HP +65 96803991
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220122529
VEHICLE NO : **SNJ 8018 D**
MODEL CODE : AUDI E-TRON 50 QUATTRO GE
MODEL YEAR : 25/10/2022
ENGINE NO : EAS 174112
CHASSIS NO : WAUZZZGE8NB047269
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Mar-23
PLACE OF ACCIDENT : 1 BILAL LANE SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNJ 8018 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	300 ✓
3	TO CARRY OUT DE-ENERGEISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION.	S/N \$ 480.00	✓ ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,350.00	600 ✓
5	TO RESPRAY FRONT BUMPER.	\$ 1,300.00	600 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 4,252.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 8018 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Delhd</i>	1	\$ 3,066.00	<i>✓ 2452.80</i>
2	FRONT BUMPER TRIM - LH / RH <i>?</i>	2	\$ 138.00	<i>? X</i>
3	FRONT BUMPER FIXING PARTS <i>Not m</i>	1	\$ 689.00	<i>X</i>
4	FRONT BUMPER CLOSING ELEMENT - CENTER <i>Cracked.</i>	1	\$ 263.00	<i>X 210</i>
5	FRONT BUMPER SUPPORT COVER - RH <i>Not m</i>	1	\$ 41.00	<i>? X</i>
6	FRONT BUMPER FOAM PART - UPPER <i>Not m</i>	1	\$ 159.00	<i>? X</i>
7	FRONT BUMPER FOAM PART - LOWER <i>Cracked.</i>	1	\$ 133.00	<i>? 106</i>
8	FRONT BUMPER PLASTIC FOAM STRIP <i>Not m</i>	1	\$ 143.00	<i>? X</i>
9	FRONT BUMPER GRILLE - LOWER CENTRE <i>} Not m</i>	1	\$ 300.00	<i>X</i>
10	FRONT BUMPER GRILLE - CENTER <i>} Not m</i>	1	\$ 181.00	<i>X</i>
11	FRONT BUMPER CLOSING ELEMENT - LOWER <i>Cracked.</i>	1	\$ 248.00	<i>X 198.40</i>
12	FRONT BUMPER AIR GUIDE - RH <i>Not m</i>	1	\$ 107.00	<i>X</i>
13	FRONT BUMPER IMPACT PROTECTION <i>ut</i>	1	\$ 953.00	<i>✓ 762</i>
14	FRONT BUMPER SPOILER - RH <i>Delhd</i>	1	\$ 117.00	<i>✓ 93.20</i>
15	FRONT BUMPER AIR GUIDE - RH OUTER <i>} Not m</i>	1	\$ 64.00	<i>X</i>
16	FRONT BUMPER AIR GUIDE - RH INNER <i>} Not m</i>	1	\$ 50.00	<i>X</i>
17	FRONT BUMPER AIR GUIDE - RH	1	\$ 141.00	<i>X</i>
18	RADIATOR GRILLE <i>Cracked</i>	1	\$ 2,466.00	<i>✓ 1972.80</i>
19	RADIATOR GRILLE COVER CAP <i>Not m</i>	1	\$ 149.00	<i>X</i>
20	RADIATOR GRILLE BRACKET <i>Not m</i>	1	\$ 111.00	<i>? X</i>
SUB TOTAL SPARE PARTS			\$ 9,519.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 8018 D
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RADIATOR GRILLE COVER	1	\$ 74.00	X
22	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 262.00	X
23	RADIATOR GRILLE COVER - RH	1	\$ 65.00	X
24	FRONT "360" CAMERA	1	\$ 1,115.00	X
25	FRONT BUMPER CROSS MEMBER	1	\$ 491.00	+
26	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,536.00	+
27	FRONT BUMPER BRACKET	1	\$ 509.00	407.20
28	FRONT BUMPER LOWER COVER	1	\$ 125.00	+
29	FRONT BUMPER UPPER COVER	1	\$ 126.00	+
30	FRONT BUMPER GUIDE SECTION - RH	1	\$ 53.00	+
31	FRONT BUMPER BRACKET - RH	1	\$ 92.00	+
32	CAUTION SIGN STICKER	1	\$ 24.00	+
33	FRONT PARKING AID SENSOR - OUTER	1	\$ 299.00	+
34	FRONT PARKING AID SENSOR - RH	1	\$ 299.00	+
35	FRONT PARKING AID SENSOR - INNER	1	\$ 299.00	+
36	FRONT PARKING AID SEAL RING	4	\$ 11.00	+
37	HEADLIGHT - RH	1	\$ 9,177.00	7341.60
38	HEADLIGHT POWER MODULE	1	\$ 876.00	+
39	HEADLIGHT HEAT SINK - RH	1	\$ 1,447.00	+
40	LIFT CYLINDER - RH	1	\$ 274.00	+
SUB TOTAL SPARE PARTS		:	\$ 17,154.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 8018 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER HOSE <i>new</i>	1	\$ 115.00	<i>+</i>
42	FRONT WHEEL COVER - LH / RH <i>new</i>	2	\$ 686.00	<i>✓</i> 548
43	RADIATOR AIR GUIDE - RH <i>new</i>	1	\$ 39.00	<i>+</i>
44	RADIATOR AIR GUIDE - LOWER FRONT <i>new</i>	1	\$ 81.00	<i>+</i>
45	RADIATOR AIR GUIDE - UPPER FRONT <i>torn</i>	1	\$ 89.00	<i>+</i> 70.80
46	FRONT LICENCE PLATE HOLDER <i>new</i>	1	\$ 229.00	<i>+</i>
47	FRONT NUMBER PLATE <i>new</i>	S/N	\$ 60.00	<i>✓</i> 60
48	SUNDRIES <i>new</i>		\$ 400.00	<i>?</i> <i>+</i>
TOTAL SPARE PARTS		:	\$ 28,372.00	
TOTAL LABOUR CHARGES		:	\$ 4,252.00	
GRAND TOTAL		:	\$ 32,624.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *04/04/23*
AUTHORISED DATE :
EXCESS COST : *4*
LIABILITY :
REMARKS : *are Authorised, 03 Days* *H.S.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT