

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLB4524B/2304050

02th April 2023

The Manager

Motor Claim Department

AIG Asia Pacific Insurance Pte Ltd

CHARTIS Building

78 Shenton Way #07-16

Singapore 079120

Like Auto Consultants hence not
the Repairer of the following:
• To survey before/after survey pricing
• To supply damaged parts, etc.
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be restocked
• subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised
1/6/23

2/59

take the 3 days.

Date of Accident : 02th April 2023

Location : Mandai Crematorium

Third Party Claim Vehicle No : GBJ 4084 E

Repair Cost For Vehicle No : SLB 4524 B Mercedes Benz S320L

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Headlamp assy RH <i>Scn</i>	1	5,500.00	\$ 5,500.00 ✓
2	Front bumper fascia <i>7019</i>	1	1,760.00	\$ 1,760.00 ✓
3	Front bumper clips <i>rm</i>	1	50.00	\$ 50.00 ✓
4	Front bumper side retainer RH <i>11</i>	1	38.00	\$ 38.00 X
5	Front fender chrome RH <i>11</i>	1	78.00	\$ 78.00 X
				\$ 7,426.00

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding front fender RH, remove & install all damage parts, straighten & re-align body	\$ 780.00 <i>300</i>
Spray painting on damage parts	\$ 780.00 <i>500</i>
Check all lighting after repairs	\$ 40.00 <i>20</i>
Diagnostic check & reset	\$ 300.00 <i>80</i>

Labour Charge \$ 1,900.00

Total Amount \$ 9,326.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.