

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LIBERTY INSURAI	NCE PTE LTD		Ref:	CS/LIP23003551/Kny3e2	
	51 CLUB STREET, LIBERTY HOUSES	, #03-00 SINGAPORE 069428		Date:	27/04/2023	
				Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNG 8743J	Veh. Inspected	l	SGN 1901L	
	Policy No.	SD22V13164	Coverage (\$)		0.00	
	Claim No.	DVS23/0050	Excess (\$)		0.00	
	Assign From	ANDY SEAH	Assign Date		05/04/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA LEXUS ES250 (A)	c.c		2494	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	JTHBJ1GG502035389	Colour		METALLIC PEARL BROWN	
	Odometer	85693 KM	Steering		JAMMED	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/55 R17	YOKOHAMA		9 mm	
	L/H Front Tyre	215/55 R17	YOKOHAMA		9 mm	
	R/H Rear Tyre	215/55 R17	YOKOHAMA		9 mm	
	L/H Rear Tyre	215/55 R17	YOKOHAMA		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND UNDERCARRIAGE.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	19/03/2023	Inspection Dat	е	05/04/2023	
	Survey held at	CARWORKZ				
		BLK10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-22 Singapore 575645				
5a.	Remarks					
	A)REGISTRATION DATE: 12 NOV 2013 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	. <b>.</b>					