

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06801

Vehicle Insured : SMW311C
Accident Date : 01-Apr-2023

Date : 04-Apr-2023

Our Ref : 023075 (ALLIANZ) / CHAN

PAGE : 1

WILLIAM WONG KWONG LAM
9E STILL LANE
Singapore 424037

Not Authorized
Resurvey B4 paint
7 days

ESTIMATED COST OF REPAIR FOR M/BENZ AVG (R18 LED) SMM8016E

- 1 pc Rear bumper fascia
- 1 pc Rear o/s bumper side retainer
- 1 pc Rear o/s fender
- 1 pc Rear o/s petrol tank lid
- 1 pc Rear o/s door
- 1 pc Rear o/s rubber
- 1 pc Rear o/s door lower chrome
- 1 pc Rear o/s sport rim
- 1 pc Rear o/s shock absorber
- 1 pc Rear o/s lower arm
- 1 pc Rear o/s knuckle arm
- 1 pc Rear o/s knuckle bearing hub
- 1 pc Rear o/s wheel bearing
- 1 pc Rear o/s lower arm (front)
- 1 pc Rear o/s top arm
- 1 pc Rear o/s thrust arm
- 1 pc Rear o/s training arm

R1	2,076.00	—
D1	111.00	—
R1	2,766.00	—
R1	195.00	X
R1	2,814.00	—
R1	303.00	50% in
R1	165.00	—
R1	883.00	—
	618.00	7
	318.00	7
	1,767.00	7
	476.00	7
	87.00	7
	261.00	7
	201.00	7
	234.00	7
	157.00	7

13,432.00

Less 10% : 1,343.20

- 1 pc Rear w/s glass sealant
- 1 pc Rear o/s door board rivet(set)

12,088.80 *Posm*
R1 60.00 sn
R1 30.00 sn

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 *120/*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMW311C

Page : 2

To remove roof lining, front and
rear seats, trim board and carpet

1201
150.00

To apply undersealing

100.00 601

To dismantle and lower rear
undercarriage

250.00 7

65.00 ✓

To check and adjust wheel alignment

1,000.00 7501

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,200.00 8001

Total : S\$15,093.80
=====

Singapore Dollars Fifteen Thousand and Ninety
Three and Cents Eighty Only