

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003563/TVP3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00219672201
Claimant Vehicle No :	SBS19Z	Insured Vehicle No :	SKA8607L
Date of Loss:	23/03/2023	Nature of Claim:	TP
		Claim No:	SNM23D202497/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS19Z	Engine No:	D9194845
Make & Model:	VOLVO B9TL, 9.4 D (A)	Chassis No:	YV3S4P924GA175822
Reg. Date:	30/12/2015 (Man. Year: 2015)	Odometer:	499784 km
Colour:	Green		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8/8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	700.00	500.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,200.00	700.00	500.00	41.67
+ GST 8.00/8.00% (S\$)	96.00	56.00	40.00	41.67
Nett Amount (S\$)	1,296.00	756.00	540.00	41.67

INSPECTION

Date of Assignment:	10/05/2023		
Date Inspected:	06/04/2023	Inspected At:	154 GUL CIRCLE SINGAPORE 629611 Repairer:Boxfresh Pte Ltd
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 May 2023)

Parts: N/A VOLVO B9TL 9.4 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBS19Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR OF FRONT OS CORNER BUMPER (NPA)	New	0.00	0.00
2	REPAIR OF FRONT OS BATTERY PANEL (NPA)	New	0.00	0.00
3	SAND ,PUTTY AND MAKE GOOD OF AFFECTED AREA	New	400.00	300.00
4	PAINTING OF AFFECTED PARTS	New	800.00	400.00
Gross Labour Cost (\$\$)			1,200.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >