



Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49
 Northstar @AMK Singapore 569880
 Tel : 64585441 Fax : 64553470

Vehicle No : SBS19Z
 Model No : Volvo
 B9tl

Accident date : 23th Mar 2023
 Registered owner : Go Ahead Singapore Pte Ltd
 Date of Estimate : 05/04/23

My Ref : BF-IC-1127

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total Charge

Parts Repair (2 days)

- a) Repair of front OS corner bumper
- b) Repair of front OS battery panel
- c) Sand, putty and make good of affected area
- d) Painting of affected parts (3 parts)

S\$400 300
 S\$800 400

2700
 + 2days

Taufik 97495749
 WP 6/4/23 @ 2:30pm
 Resurvey after repair
 Taufik @ Khantoum

Subtotal S\$ 1200
 Total Charge S\$ 1200
 GST 8% S\$ 96
 Total Bill S\$ 1296

BOXFRESH PTE LTD
 WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611
 OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880
 T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg