



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS3/SPF23003564/Wqy3m4

ACCIDENT CLAIMS SECTION (SPORE POLICE
FORCE) POLICE LOGISTICS BASE (PLB) 1
HEMMANT ROAD SINGAPORE 438675

Date: 28/04/2023

ATTN: HAFIZUL FARHAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 1739T	Veh. Inspected	SLH 5485S
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/019	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	04/04/2023

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL HYBRID 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31213955	Colour	RED
Odometer	270655 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FARROAD	6 mm
L/H Front Tyre	215/60 R16	FARROAD	6 mm
R/H Rear Tyre	215/60 R16	FARROAD	6 mm
L/H Rear Tyre	215/60 R16	FARROAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/03/2023	Inspect Date / Time	06/04/2023 (11:45 AM)
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days