

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Ergo Insurance Pte Ltd
 5 Temasek Boulevard
 #04-01 Suntec Tower Five
 Singapore 038985
 Tel : 6829 - 9170
 Fax : 6829 - 9247

Quotation
 DATE : 06.04.2023
 VEH NO : SLK3519B
 MODEL : Honda Shuttle
 D O A : 03.04.2023
 YR REF : SKX9838J

VERON

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLK3519B (HONDA SHUTTLE)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Disturbed</i>	1	986.90 ✓
2	Rear Bumper Reflector <i>new</i>	2	90.40 +
3	Rear Bumper Reflector Garnish <i>Del'd</i>	2	90.80 ✓
4	Rear Bumper Towing Cover <i>new</i>	1	19.00 +
5	Rear Bumper Side Retainer <i>new</i>	2	64.00 ✓
6	Rear Bumper Side Sponge <i>new</i>	2	94.00 ✓
7	Tailgate <i>Disturbed</i>	1	1,193.20 ✓
8	Tailgate Outer Chrome Moulding <i>new</i>	1	383.80 +
9	Tailgate Logo <i>new</i>	1	38.40 +
10	Tailgate Shuttle Emblem <i>new</i>	1	55.40 +
11	Tailgate Lamp <i>LH cut</i>	2	761.80 <i>380.90</i>
12	Tailgate Inner Lock <i>Disturbed</i>	1	298.40 ✓
13	Tailgate Lock Catch <i>new</i>	1	24.00 +
14	Tailgate Weatherstripe <i>cut</i>	1	166.50 ✓
15	Tailgate Lock Antenna <i>new</i>	1	180.20 +
16	Tailgate Inner Trim Board <i>Del'd</i>	1	320.40 ✓
17	Tailgate Windscreen Moulding <i>new</i>	1	149.20 ✓
18	Tailgate Buzzer <i>new</i>	1	170.00 +
19	Tail Lamp <i>LH cut</i>	2	1,041.00 <i>520.50</i>
20	Rear End Panel <i>Disturbed</i>	1	681.20 ✓
21	Rear End Panel Top Garnish <i>Del'd</i>	1	155.00 ✓
22	Rear Floor Panel Top Outer Board <i>new</i>	1	585.20 +
23	Rear Plastic Storage Box <i>Del'd</i>	1	495.00 ✓
24	Rear Tools Sponge Tray <i>new</i>	1	265.40 ✓
25	Rear Jack Cover <i>Del'd</i>	1	122.40 ✓
			\$ 8,331.60
			(1,666.32)
			6792.80
			5434.24

Rear Fender Inner Trim Board 2
Del'd
 Less 20%
399
2 = 798

RE : ESTIMATE FOR ACCIDENT REPAIR SLK3519B (HONDA SHUTTLE)

\$ 6,665.28

S/NETT ITEMS

1	Rear Bumper Clips <i>new</i>	1 set	50.00 30
2	Tailgate Outer Chrome Moulding Clips <i>new</i>	1 set	30.00 +
3	Tailgate Windscreen Sealant <i>new</i>	1	60.00 ✓
4	Tail Lamp Clips <i>new</i>	1 set	20.00 10
5	Rear End Panel Sealant <i>new</i>	1	60.00 ✓
6	Rear End Panel Top Garnish Clips <i>new</i>	1	20.00 ✓
7	Reverse Sensor <i>new</i>	1	280.00 200
8	Rear Camera <i>new</i>	1	480.00 +
9	Tailgate Surround Moulding <i>new</i>	1	250.00 150
			1,250.00
Rear Fender Zone Train Board Clips <i>new</i> 60 ✓			
Total Parts			\$ 7,915.28

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 1,200.00 <i>ho</i>
2	To putty & spray up paint works	\$ 1,200.00 <i>ho</i>
3	To check wiring	\$ 50.00 30
4	To spray tuff coat	\$ 150.00 80
5	To remove upholstery	\$ 150.00 80
6	To remove tailgate glass	\$ 180.00 120
7	To transfer tailgate fittings	\$ 150.00 80
8	To remove reverse sensor	\$ 100.00 50
9	To remove rear camera	\$ 100.00 50
		\$ 3,280.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Insurance claim(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

GST Will be reflected in the final bills

NOTE : -

Acknowledged by Repairer

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

\$ 11,195.28

Total: 8114.24

L/S: 6.5K.

06 Days