



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 2482Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR CARGO BOX COMPANY DECAL O/S (SN)	NECESSARY	3,800.00	2,000.00
3	REAR CARGO BOX ALUMINIUM PANEL O/S (SN)	CRACKED	4,000.00	3,800.00
			7,800.00	5,800.00
	<b><u>LABOUR</u></b>			
	LABOUR TO REMOVE, CUT, CHANGE DAMAGED ITEMS.		3,800.00	600.00
	TO PUTTY AND RESPRAY AFFECTED AREAS.		2,800.00	800.00
			6,600.00	1,400.00
	<b>GRAND TOTAL</b>		<b>14,400.00</b>	<b>7,200.00</b>
<b>RECOMMENDED COST OF REPAIR SUM</b>				<b>6,100.00</b>

Report Ref No. CS/LAW23003569/Uny3e2

NOTE: NEW PARTS REPLACEMENT

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.