



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HOLMAN FENWICK WILLAN SINGAPORE LLP 30 RAFFLES PLACE, #24-01, OXLEY @ RAFFLES, SINGAPORE 048622			Ref: CS/LAW23003569/Uny3e2 Date: 12/05/2023 Code: L181	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SATS BAGGAGE TROLLEY		Veh. Inspected	YP 2482Z
Policy No.			Coverage (\$)	0.00
Claim No.	67925-343		Excess (\$)	0.00
Assign From	DARRYL ANDREW QUEK		Assign Date	04/04/2023
2. Vehicle Particulars & Condition				
Make & Model	UD TRUCKS MKB8		c.c	7013
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	JNCL0D0A2GU003329		Colour	WHITE
Odometer	213789 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/75 R17.5	FIRENZA	6 mm	
L/H Front Tyre	235/75 R17.5	FIRENZA	6 mm	
R/H Rear Tyre	235/75 R17.5 (D)	FIRENZA	6/6 mm	
L/H Rear Tyre	235/75 R17.5 (D)	FIRENZA	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/03/2023		Inspection Date	06/04/2023
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	