

37	BOOTLID OUTER GARNISH <i>Del'd</i>	1	\$	215.10	\$	215.10	✓
38	BOOTLID INNER TRIM <i>new</i>	1	\$	182.30	\$	182.30	✓
39	HONDA LOGO <i>new</i>	1	\$	35.60	\$	35.60	✓
40	i-VTEC EMBLEM <i>new</i>	1	\$	40.80	\$	40.80	✓
41	CIVIC EMBLEM <i>new</i>	1	\$	39.40	\$	39.40	✓
42	REAR FENDER INNER TRIM <i>new</i>	2	\$	258.20	\$	516.40	✓
43	REAR FENDER INNER SHIELD <i>new</i>	2	\$	145.30	\$	290.60	✓
44	SPARE TYRE PANEL <i>new</i>	1	\$	656.40	\$	656.40	✓
45	SPARE TYRE PANEL TOP BOARD <i>new</i>	1	\$	195.80	\$	195.80	✓
46	REAR EXHAUST PIPE <i>new</i>	1	\$	654.20	\$	654.20	✓
47	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$	35.10	\$	35.10	✓
48	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$	30.20	\$	30.20	✓
49	REAR EXHAUST HEAT SHIELD <i>new</i>	1	\$	95.80	\$	95.80	✓

9289.30

7431.44

TOTAL PRICE: \$ 17,891.30
 LESS 20% \$ 3,488.04
 SUB TOTAL PRICE: \$ 13,952.16

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	FRONT NUMBER PLATE <i>Best</i>	1	\$ 30.00	\$ 30.00	✓
2	FRONT NUMBER PLATE HOLDER <i>Del'd</i>	1	\$ 30.00	\$ 30.00	✓
3	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
4	FRONT GRILLE <i>cracked</i>	1	\$ 500.00	\$ 500.00	✓ 450
5	FRONT GRILLE CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
6	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
7	AIR CON CONDENSER SIDE GUIDE CLIPS <i>new</i>	2 SET	\$ 20.00	\$ 40.00	✓
8	RADIATOR COOLANT <i>new</i>	1	\$ 50.00	\$ 50.00	✓
9	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
10	REVERSE SENSOR <i>Del'd</i>	1	\$ 280.00	\$ 280.00	✓ 200
11	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
12	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00	✓
13	BOOTLID OUTER GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
14	BOOTLID INNER TRIM CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
15	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00	✓
16	REAR FENDER INNER TRIM CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00	✓
17	REAR FENDER INNER SHIELD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00	✓

*Rees Bumper Top Garnish: Del'd 350.
 Rees Bumper Lower Garnish chg missing 480*

TOTAL: \$ 1,780.00

1670

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 2,400.00	1300	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,200.00	1300	
3	WIRING CHECK	\$ 150.00	60	
4	TO APPLY TUFF COAT	\$ 280.00	100	
5	TO REMOVE CONDENSER & TOP UP AIR CON GAS	\$ 120.00	80	
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	\$ 120.00	80	
7	TO REMOVE UPHOLSTERY & REAR SEAT	\$ 400.00	80	
8	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
9	TO REMOVE REAR CAMERA	\$ 100.00	50	
10	TO TRANSFER BOOTLID FITTINGS	\$ 150.00	80	
11	TO REMOVE REAR EXHAUST PIPE	\$ 150.00	x	
12	TOWING FEES	\$ 60.00	x	

3180

TOTAL: \$ 6,230.00

ESTIMATE REPORT

TOTAL PARTS COST:	\$	15,732.16
TOTAL LABOUR COST:	\$	6,230.00
TOTAL REPAIR COST:	\$	21,962.16

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

total: 12281.44
2/s: 9.81k
10 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9.81k