

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

Not Noted
1/1/2023 @ 3100h
Repair After Paint
4 days

UNIQUE TOURIST SERVICE PTE LTD

c/o 46 Lentor Plain

Singapore 786548

Date: 5/4/2023

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA WISH / SLU 1162 G		
1 pc	rear boot lid	1,582.20 ✓
1 pc	rear boot lid lock	472.50 X
1 pc	rear boot lid lock catch	96.40 X
1 pc	rear boot lid emblem "LOGO"	84.50 —
1 pc	rear boot lid emblem - VLAVE MATIC	85.10 —
1 pc	rear boot lid emblem ELEGRANT	78.40 —
1 pc	rear bumper	499.80 —
2 pcs	rear bumper bracket @ 85.60	171.20 X
2 pcs	rear bumper reflector @ 141.50	283.00 X
2 pcs	rear bumper corner retainer @ 56.70	113.40 4x
2 pcs	rear bumper side retainer @ 68.40	136.80 4x
2 pcs	rear bumper impact bracket @ 96.60	193.20 X
1 pc	rear end panel	700.60 X
1 pc	rear end panel inner trim	198.40 X
1 pc	rear end panel top garnish	429.30 X
3 pcs	rear windscreen moulding @ 128.20	384.60 —
Sub-total		5,509.40
Less 25%		1,377.35
Sub-total		4,132.05
1 set	reverse sensor s.nett	220.00 200sn
1 pc	rear windscreen inner seal s.nett	60.00 30sn
1 tube	windscreen glass sealant s.nett	60.00 40sn
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		1,000.00 500d
To spray painting on affected areas.		950.00 60d
To apply rust proofing.		150.00 30d
To apply waterproof sealant on affected areas.		150.00 X
To remove and refit rear windscreen glass.		140.00 120d
To transfer tail door accessories.		60.00 ✓
To install reverse sensors.		80.00 50d
Total		7,002.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: