

ASS. REC. BY:

REF:

Smo/23 0035721K_N

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4.5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) S - RS. SI

) F. P. S.

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Vehicle:

SLU 1182G

Yr Regn:

11, 17

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

c.c

1798

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

107209

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDGG 20W80J008303

Gen. Cond: Good / Fair / Poor / Burnt

Steer: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A:

1/4/23

D.O.I:

6/4/2023

Survey held at

11:50am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

Not Notified
1/1/2023
Returning After Repair
4-5 days

UNIQUE TOURIST SERVICE PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Date: 5/4/2023

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA WISH / SLU 1162 G		
1 pc	rear boot lid	1,582.20 ✓
1 pc	rear boot lid lock	472.50 ?
1 pc	rear boot lid lock catch	96.40 X
1 pc	rear boot lid emblem "LOGO"	84.50 —
1 pc	rear boot lid emblem - VLAIVE MATIC	85.10 —
1 pc	rear boot lid emblem ELEGRANT	78.40 —
1 pc	rear bumper	499.80 ✓
2 pcs	rear bumper bracket @ 85.60	171.20 X
2 pcs	rear bumper reflector @ 141.50	283.00 X
2 pcs	rear bumper corner retainer @ 56.70	113.40 4x
2 pcs	rear bumper side retainer @ 68.40	136.80 4x
2 pcs	rear bumper impact bracket @ 96.60	193.20 ?
1 pc	rear end panel	700.60 ?
1 pc	rear end panel inner trim	198.40 X
1 pc	rear end panel top garnish	429.30 X
3 pcs	rear windscreen moulding @ 128.20	384.60 ✓
Sub-total		5,509.40
Less 25%		1,377.35
Sub-total		4,132.05
1 set	reverse sensor s.nett	220.00 2000
1 pc	rear windscreen inner seal s.nett	60.00 3000
1 tube	windscreen glass sealant s.nett	60.00 4000
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		1,000.00 ?
To spray painting on affected areas.		950.00 600
To apply rust proofing.		150.00 ?
To apply waterproof sealant on affected areas.		150.00 ?
To remove and refit rear windscreen glass.		140.00 1200
To transfer tail door accessories.		60.00 ✓
To install reverse sensors.		80.00 500
Total		7,002.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/04/2023 14:01 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	01/04/2023 13:25 (SGT)
Exact Location of Accident	Second Link Expy, Malaysia
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU1162G
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Unique Tourist Service (Pte) Ltd
Company Reg No	197401067R
Email Address	uniqtour@singnet.com.sg
Mobile Phone No	(Phone) +65-96196272
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Wish
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	7990000144/12200042221

DRIVER

Name of Driver	Marc Niebuhr
Passport No/FIN	G3931713W
Date Of Birth	27/09/1975
Occupation	Indoor

ACCIDENT MARC NIEBUHR (SLU1162G)/JUMARI SIBI (SJJ7535G) on Tuas Second Link

Date and time: 1 Apr 2023; 13:25 and 14:04

Involved parties

	Own vehicle	Other party
Vehicle number	SLU1162G	SJJ7535G
Name driver	MARC NIEBUHR	JUMARI SIBI
NRIC/FIN	G3931713W	S1684811E (National ID from passport)
Phone	+65 9653 0659	+65 9855 2627
Address	74 Gentle Drive 309276 Singapore	Blk 250 Jurong East St24 #07-142 S600250
Insurer		<i>Driver prefers not to involve his insurance</i>

Scene

Location: Tuas Second Link; Second Link Expressway; Driving from Singapore to Malaysia

