



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23003574/Tvy3e2	
			Date: 17/07/2023	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SG 5970E	Veh. Inspected	SGD 99L
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/03/23/7037	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	05/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ CLA180	c.c	1332
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	W1K1183842N146704	Colour	BLACK
	Odometer	21400 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/45 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/45 R18	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	29/03/2023	Inspection Date	06/04/2023
	Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
<b>5a. Remarks</b>				
	A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	