



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

|              |             |
|--------------|-------------|
| Our Ref      | : UC734     |
| Vehicle No.  | : SMJ9756L  |
| Make & Model | : HONDA FIT |

Page No. 1

| QTY                           | DESCRIPTION                             | CONDITION | REPAIRER'S ESTIMATE(S\$) | SURVEYOR'S ADJUSTMENT |
|-------------------------------|-----------------------------------------|-----------|--------------------------|-----------------------|
| <b>PARTS (LIST ITEMS)</b>     |                                         |           |                          |                       |
| 1                             | Boot lid                                |           | 889.00                   | bf -                  |
| 1                             | Boot lid lock                           |           | 158.00                   | ?                     |
| 1                             | Boot lid weather strap                  |           | 93.00                    | ?                     |
| 1                             | Boot lid emblem "FIT"                   |           | 35.00                    | net -                 |
| 1                             | Rear windscreen moulding                |           | 139.00                   | net -                 |
| 1                             | Rear bumper                             |           | 530.00                   | de -                  |
| 2                             | Rear bumper side retainer RH/LH@2*\$119 |           | 238.00                   | ?                     |
| 2                             | Rear fog lamp cover RH/LH@2*\$41        |           | 82.00                    | X                     |
| 1                             | Rear bumper lower garnish               |           | 65.00                    | Rp                    |
| 1                             | Rear bumper lower skirt                 |           | 95.00                    | Rp                    |
| 1                             | End panel                               |           | 400.00                   | Rp                    |
| 1                             | End panel top garnish                   |           | 66.00                    | X                     |
|                               |                                         |           | <b>2790.00</b>           |                       |
| <b>Part Items Total: -20%</b> |                                         |           | <b>-558.00</b>           |                       |
|                               |                                         |           | <b>2232.00</b>           |                       |
| <b>SPECIAL NETT ITEMS</b>     |                                         |           |                          |                       |
| 1                             | Rear bumper clip                        |           | 35.00                    | net -                 |
| 1                             | Rear windscreen sealant                 |           | 60.00                    | net -                 |
| 1                             | Rear reverse sensor                     |           | 200.00                   | net -                 |
| 1                             | End panel sealant                       |           | 60.00                    | X                     |
| <b>SN Items Total:</b>        |                                         |           | <b>355.00</b>            |                       |
| <b>Total Parts:</b>           |                                         |           | <b>2587.00</b>           |                       |



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC734  
Vehicle No. : SMJ9756L  
Make & Model : HONDA FIT

Page No. 2

| S/N                                | DESCRIPTION                                                                                                                                       | REPAIRER'S ESTIMATE (\$) | SURVEYOR'S ADJUSTMENT |
|------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-----------------------|
| <b>LABOUR</b>                      |                                                                                                                                                   |                          |                       |
| 1                                  | To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components | 1000.00                  | 600                   |
| 2                                  | To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired                                                   | 800.00                   | 600                   |
| 3                                  | To perform anti-rust treatment on affected areas                                                                                                  | 60.00                    | 30                    |
| 4                                  | To remove and refix wiring system at accident damaged area and check for all electrical proper function                                           | 90.00                    | 30                    |
| 5                                  | To carried out remove and refix rear windscreen                                                                                                   | 100.00                   | ✓                     |
| 6                                  | To remove and replace rear reverse sensor                                                                                                         | 100.00                   | 30                    |
| <b>Labour Total :</b>              |                                                                                                                                                   | <b>2150.00</b>           |                       |
| <b>TOTAL (PARTS &amp; LABOUR):</b> |                                                                                                                                                   | <b>4737.00</b>           |                       |

Auto Consultants hence notify  
Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No alteration/modification(s) is allowed  
• Supplementary item(s) must be resurveyed  
• Subject to final approval from Insurance Company  
Acknowledged by Repairer  
Signature: *Tan Jiah 97495749/62563561*  
*8/5/23 @ 5:55pm*  
*Tan Jiah e/khant.wn*  
*4 = 5 days*  
*4/5 resurvey after repair.*