

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4513K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER COVER	TORN	586.18	586.18
1	BONNET HINGE RH	NOT NECESSARY	87.70	-
1	FRONT FENDER RH	BENT	1,111.93	1,111.93
1	FRONT FENDER SHIELD RH	TORN	198.50	198.50
1	FRONT FENDER EMBLEM RH	NECESSARY	88.00	88.00
1	FRONT BUMPER TOW COVER	MISSING	28.38	28.38
1	FRONT GRILLE EMBLEM	NECESSARY	88.00	88.00
1	HEAD LAMP PANEL RH	NOT NECESSARY	240.10	-
1	RADIATOR STAY SUPPORT RH	NOT NECESSARY	278.68	-
1	WASHER SPARE TANK	DEFORMED	183.75	183.75
1	FRONT HEAD LAMP RH	CRACKED	2,637.60	2,637.60
1	FRONT BUMPER DAY LIGHT RH	CRACKED	99.00	99.00
1	FRONT WHEEL HUB COVER	NOT NECESSARY	189.60	-
2	FRT BUMPER SIDE RETAINER RH/LH @\$77.00	N/S NOT NECESSARY / O/S DEFORMED	154.00	77.00
	LESS 25% DISCOUNT		-1,492.86	-1,274.59
			4,478.56	3,823.75
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK WIRING.		60.00	30.00
	RESET WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
			1,420.00	880.00
	GRAND TOTAL		5,898.56	4,703.75





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,700.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC23003584/Twp3e2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.