

Our Job Ref No : 305550671 Data 20 04 2023

ComfortDelGro Engineering Pte I td

Date		*	20.04.2023		59 Loyang Drive Singapore 508969				
To	To: LKK				Fax :				
Attn : TAUFIKH									
Vehi	icle Re	g No. : SHA	4513K			03.04.2023			
The	survey	and estimates o	f the repairs of the above-n	nentioned vehic	le are as follo	ws:-			
Z	The repair job shall bill to:			INCOME	Ē	SLF4763G			
2.	The finalized amount shall be:					<del></del>			
	(a)		ter List discount						
	(b)	Labour Charge							
	(0)		s By-Part Repair Cost			()			
		rotal for rait	by-r art Repair Cost			\ <del></del>			
	(c.)		air (if applicable) sum repair cost after Less: <b>m Repair cost</b>		_	<b>\$27,59,29</b> \$37,00			
<ul><li>3.</li><li>4.</li></ul>	We s	nated normal per hall treat the ab rking days	ove amount as Correct a		orking days. if there is no	reply from you within			
5.	Thank you for your assistance.				e confirm the nalized amoun	estimates and it			
	Signature :				gnature:	taufikh			
	Name : CHIANG			Na	Name : Taufikh				
	Tel : 62148314			Da	Date : 12/5/23				
	Fax	6546815	6	_					
For C	Official	Use Only							
	ı	ltem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks			
1. Re	Rental Rate P/Day			YES					
2. Loss of Income Paid -			N						
3. Survey Fees				-					

6 Overrun			1
Remarks:			76

YES

\$26.75/\$2.00

LTA Search Fee
Medical Fees (on behalf of driver, if applicable)

## COMFORTDELGRO ENGINEERING PTE LTD

**VEHICLE NO** 

REG .31.05.2019

**DATE 03.04.2023** 

MODEL	PRIUS G4	CHIANG/INCOME			
Qty	Parts Description/ Labour	Туре	Unit Price	Amount	
	1 FRT BUMPER COVER			M~\$586.18	
	1 BONNET HINGE RH			\$87.70	
	1 FRONT FENDER RH		2 * 2	ht \$1,111.93	
8 B	1 FRONT FENDER SHIELD RH			\$198.50	
	1 FRONT FENDER EMBLEM RH			\$88.00	
	FRONT BUMPER TOW COVER	7	'	\$28.38	
9 1	FRONT GRILLE EMBLEM	120		\$88.00	
	HEAD LAMP PANEL RH			× -\$240.10	
1	RADIATOR STAY SUPPORT RH			× \$278.68	
Sec. 1	WASHER SPARE TANK		9	\$183.75	
* 1	FRONT HEAD LAMP RH			\$2,637.60	
2 1	FRONT BUMPER DAT LIGHT RH			\$99.00	
1	FRONT WHEEL HUB COVER			× -\$189.60	
.1	FRT BUMPER SIDE RETAINER RH /LH		LHX \$77.00	MILL P	
€ 5	SUB TOTAL			\$5,971.42	
	LESS 25%			\$1,492.85	
14	DISCOUNTED TOTAL	A .		\$4,478.56	
30° 20		Laren II	5		
			all a	N.	
	e s		4	,-	
	a **				
	Labour Charge				
	Panel Beating	*	3	\$700.00	
	Spray Painting Charge	ı	5	\$600.00	
* "	Check Wiring			30 \$60.00	
	Reset Eheel Alignment			\$60.00	
*	TOTAL LABOUR			\$1,420.00	
2020	ESTIMATE TOTAL			ÅF 000 F5	
- 1	ESTIMATE TOTAL			\$5,898.56	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.