

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En	Automo	bile CS3/	AWA2200272
	ALLIED WORLD A	-	Ref:	CS3/AWA22002726/Rgy3		
	(SINGAPORE BRA 60 ANSON ROAD MAPLETREE ANS SINGAPORE 0799	#08-01 (8th FLOOR) ON		Date:	24/03/2022	04/04/2023
				Code:	AWA	
1.		Policy Particulars :-	(THIRD PARTY	CLAIN	<b>1</b> )	
	Insured Veh.	YQ 3819A	Veh. Inspected		SMW 6686G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	NSV2200035/HLF	Excess (\$)		0.00	
	Assign From	GOH STELLA HEW LEE FONG	Assign Date		24/03/2022	04/04/2023
2.		Vehicle Partic	ulars & Conditi	on		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	Steering				
	Brakes		Modification			
	General					
3.		T	ons of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.		Description	on of Damages			
5.		General	Information			
	Accident Date	18/03/2022	Inspection Dat	e	28/03/2022	
	Survey held at	REVOL CARZ GARAGE PTE LT	·			
	-	BLOCK 10, ANG MO KIO IND PARK 2A #02-18, AMK AUTOPOINT SINGAPORE 568047				
5a.		Re	emarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					