

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 06 Apr 2023

Preliminary Advice

Vehicle No	: SNB2972E	Accident Date	: 29/03/2023
Make	: MAZDA 3	Policy No.	: SP2003057670
Assignment Date	: 06/04/2023	Excess	: S\$1,500.00
Date of Inspection	: 06/04/2023	Est. Duration of Repair	: 8
Inspection At	: SV AUTOWORKS PTE LTD (HQ) 8 KAKI BUKIT AVENUE 4, #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,752.61
Revised Amount	:S\$	20,018.42
Check Items (Estimated)	:S\$	2,392.46
Total	:S\$	22,410.88

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	41,468.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,532.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.