

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003588/NVP3M4**Date:** 18/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00265122100

Claimant Vehicle No : SBS3439A **Insured Vehicle No :** SMQ2387C

Date of Loss: 02/04/2023 Nature of Claim: TP Claim No: SNM23D202542/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS3439A**

Make & Model: VOLVO B9TL, 9.4 D AUTO TURBO ABS (A) Engine No: D9193289

Reg. Date: 03/11/2014 (Man. Year: 2014) Chassis No: YV3S4P92XFA169117

Colour: Green Odometer: 500442 km

Engine Capacity: 9364 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D/D)

Front Left Side: Firenza 23 mm Rear Left Side: Firenza 17/14 mm

Front Right Side: Firenza 23 mm Rear Right Side: Firenza 17/14 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,006.07	8,070.97	1,935.10	19.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,900.00	5,100.00	4,800.00	48.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,906.07	13,170.97	6,735.10	33.83
+ GST 8.00/8.00% (S\$)	1,592.49	1,053.68	538.81	33.83
Nett Amount (S\$)	21,498.56	14,224.65	7,273.91	33.83

INSPECTION

Date of Assignment: 06/04/2023

Date Inspected: 06/04/2023 Inspected At: LEXBUILD INTERNATIONAL PTE LTD - LOYANG WAY (HQ)
LOYANG BUS DEPOT, 2 LOYANG WAY
SINGAPORE 508776

Estimated Period of Repair: 4.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$13,170.98

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 May 2023)	
Parts:	N/A	VOLVO B9TL 9.4 D AUTO TURBO ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS3439A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHS 1ST WHEELARC PANEL TBC (NPA)	Repair	0.00 F	*- FL
2	1		*RHS 3RD BODY PANEL	Dented	628.57 F	*628.57 FL
3	1		*RHS 4TH BODY PANEL	Dented	839.18 F	*839.18 FL
4	1		*RHS FUEL PANEL	Dented	3,018.44 F	*2,500.00 FL
5	1		*RHS 2ND WHEELARC PANEL	Dented	2,768.37 F	*2,500.00 FL
6	1		*RHS 3RD WHEELARC PANEL	Dented	2,651.51 F	*2,400.00 FL
7	1		*DIESEL STICKER	Necessary	50.00 F	*50.00 FL
8	1		*ADBLUE STICKER	Necessary	50.00 F	*50.00 FL
					Sub Total (S\$)	10,006.07 8,967.75
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 896.78
					Total Parts (S\$)	10,006.07 8,070.97

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY SKILLED LABOUR TO REPLACE - RHS 3RD BODY PANEL - RHS 4TH BODY PANEL - RHS FUEL PANEL - RHS 2ND WHEELARC PANEL - RHS 3RD WHEELARC PANEL	New	4,800.00	2,000.00
2	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO PUTTY, GRINDING & SPRAYPAINT - RHS 1ST WHEELARC PANEL - RHS 3RD BODY PANEL - RHS 4TH BODY PANEL - RHS FUEL PANEL - RHS 2ND WHEELARC PANEL - RHS 3RD WHEELARC PANEL	New	4,800.00	2,800.00
3	SUPPLY LABOUR & ADVERTISEMENT STICKER	New	300.00	300.00
Gross Labour Cost (\$\$)			9,900.00	5,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >