

COMFORTDELGRO ENGINEERING PTE LTD

SAS-KIV

Updated 1 November 2020

REPAIR ESTIMATE

LKK -

DATE: 05.04.2023

SLZ9719Y

INSURANCE: INCOME (LIS)

MODEL: Hyundai i40

MVA: LIM T S

VEHICLE NO.: SHA1539G

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Radiator Grille H Emblem	1		\$129.50	/NEC
	Radiator Grille	1		\$1,480.00	/CRA
	Front Bumper	1		\$1,052.20	/DEF
	Front Bumper Clips	10	2.20	\$22.00	/NEC
	Front Bumper Sponge	1		\$379.20	/CRA
	Front Bumper Reinforcement	1		\$588.40	? / DD
	HeadLamp LH	1		\$1,388.00	/CRA
	HeadLamp Support Panel	1		\$907.40	? X SVL
	Bonnet	1		\$2,508.80	X R
	Front Fender LH	1		\$663.00	X R / DD
	SUB TOTAL		5,702.30	\$9,118.50	
	LESS 20%			\$1,823.70	
	DISCOUNTED PARTS TOTAL		4,561.84	\$7,294.80	
	Front No. Plate With Trim Cover	1		\$55.00	/CRA
	S/NETT LESS 10%			\$5.50	
	S/NETT TOTAL			\$49.50	
	Labour Charge				
	Panel Beating			\$600.00	560
	Spray Painting Charge			\$900.00	750
	Tuff Kote			\$60.00	40
	Check Lightings			\$40.00	30
	R/I Radiator etc			\$120.00	X/N
	TOTAL LABOUR		5,991.34	\$ 1,720.00	
	ESTIMATE TOTAL			\$ 9,064.30	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NA2 LKK
 5/4/2023 1610
 LIS
 3 DAYS
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS

The following:
 • Panel Beating
 • Spray painting
 • Part(s) during resurvey
 • Part(s) subject to confirmation
 • Part(s) on a "Without Prejudice" basis
 • Part(s) is allowed
 • Part(s) must be resurveyed and
 • Part(s) approval from Insurance Company

Acknowledged: Repairer
 Signature:
 Date: