

ASS. REC. BY:

REF:

1CS/23803594/kgz3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STS 75568

Yr Regn:

09, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

c.c

1339

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

107843

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMG E 085095215222

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Falken

Front

Rear

R/Bal.

8

mm

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

3/4/23

D.O.I.

6/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/4 11:20 @ 1450. Carbody used 4871.10, 38%

Date/Time, File Pass to?

☐

: Prell. Report

1) 14/4 11:20

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format:

MER-OD

Lump Sum / I.B.F. (\$

1450

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	705J

Vehicle Details

Vehicle No.:	SJS7556Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Apr 2023
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3L AT
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L13Z11015220
Chassis No.:	JHMGE68509S215222
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$20,064.00
Original Registration Date:	01 Sep 2009
First Registration Date:	01 Sep 2009
Transfer Count:	4
Actual ARF Paid:	\$20,064.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 May 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,943.00
COE Rebate Amount:	\$3,208.00
Total Rebate Amount:	\$3,208.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Apr 2023

OK

Alan's United Auto Pte Ltd (Co.Reg.No:201113667N)

Blk 7 Sin Ming Industrial Estate, #01-76

Singapore 575642

Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com;Janicechou@alanutd.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	023077
Policy No:	MPC23P00052000	Date of Loss:	03/04/2023
Vehicle Reg. No.:	SJS7556Z	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SITI HANISAH BINTE ZAINAL ABIDIN	Contact No:	+6581137273
Driver:	ANDI BASTIAN BIN ICHWAN NYOMA		
Make/Model:	HONDA JAZZ, 1.3 L (A)	Vehicle Reg. Date:	01/09/2009
Vehicle Colour:	GREY		
Engine No:	L13Z11015220	Chassis No:	JHMGE685095215222
Odometer:	0 KM		
Paint Type:			<i>NOT whitened</i>
Total Loss?	NO		<i>11 Sing &</i>
Est. Duration of Repair (day)	3 ✓		<i>Heavy After Rain</i>
Present Location:	ALAN'S UNITED AUTO PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	1,101.10
Miscellaneous Items	0.00
Labour	1,220.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,321.10
+ GST 8.00% (S\$)	185.69
Nett Amount (S\$)	2,506.79

This claim is handled by: **CHAN YEW SIAH**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Apr 2023)

Parts: 144 HONDA JAZZ 1.3 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Alan's United Auto Pte Ltd/SJS7556Z/04/04/2023 14:00

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT RH FENDER	By 0.00	0.00	*220.00 F	✓
2	1		*RH HEADLAMP	Br 0.00	0.00	*300.00 F	✓
3	1		*RH HEADLAMP LOWER BRACKET		0.00	DIT *45.00 F	✓
4	1		*FRONT BUMPER FASCIA	Br/LM 0.00	0.00	*330.00 F	✓
5	1		*FRONT RH BUMPER SIDE RETAINER	DIT 0.00	0.00	*16.00 F	✓
6	1		*FRONT W/S GLASS WASHER TANK		0.00	Sw *90.00 F	X

F=Franchise part.

Sub Total (S\$)	1,001.00
+ Margin on L,N Items 10.00% (S\$)	100.10
Total Parts (S\$)	1,101.10

Alan's United Auto Pte Ltd/SJS7556Z/04/04/2023 14:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REWIRE DAMAGED PARTS & REFOCUS HEADLAMP BEAM	New	20.00 ✓
2	TO PUTTY AND SPRAY REPLACED PARTS	New	400/ 700.00
3	TO REMOVE ,CUT OUT DAMMAGED PARTS , PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	400/ 500.00
Gross Labour Cost (\$\$)			1,220.00

Alan's United Auto Pte Ltd/SJS7556Z/04/04/2023 14:00. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >