

Our Job Ref No : 305550784

Date : 08/04/23

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. : SHA3787T

05.04.2023

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **INCOME** -- **FBR9485G**
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost** **\$0.00**
- (c.) Lumpsum Repair (if applicable)
- Total for Lumpsum repair cost after Less: 20% **\$1,850.00**
- Final Lumpsum Repair cost** **\$1,850.00**

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : NAZ LKK

Date : 21/4/2023

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$26.75 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3787T  
Make : HYUNDAI  
Model : IONIQ

Date: 05/04/2023  
Insurance: INCOME  
MVA: MS. LOKE YY L/S.

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER / CRA			\$459.40
10	REAR BUMPER CLIPS / NEC			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY / DEF			\$451.25
1	REAR BUMPER REFLECTOR LH ? XSVL			\$32.00
1	TAIL LAMP LH / CRA			\$935.40
1	REAR BUMPER TOWING COVER X SVL			\$98.80
1	REAR BUMPER SIDE BRACKET LH ? XSVL			\$55.80
	SUB TOTAL			\$2,054.65
	LESS 20%			\$410.93
	DISCOUNTED TOTAL			\$1,643.72
	REAR BUMPER REVERSE SENSOR / DEF			\$180.00
			NETT	\$180.00
	Labour Charge			
	PANEL BEATING			350 \$400.00
	SPRAY PAINTING CHARGE			250 \$300.00
	CHECK LIGHTING			30 \$60.00
	REMOVE/REFIX REVERSE SENSOR			30 \$80.00
	TOTAL LABOUR			\$840.00
	ESTIMATE TOTAL			\$2,663.72

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKIC  
5/4/2023 1604  
LIS  
2 DAYS  
CHECK ITEM PHOTOS  
AFTER REPAIR PHOTOS

LKK Auto Corporation hereby certify the Repairer to the following

- To resurvey the vehicle after repair
- To display damaged parts for survey
- Parts prices are subject to market price
- Third party survey is on a "no prejudice" basis
- No ill-effects to the vehicle
- Supplementary documents are surveyed and is subject to the approval of the Insurance Company

Acknowledged by Repairer  
Signature:  
Date: