

ASS. REC. BY:

REF:

PC2/230035961/kny3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: B 62k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SCW 382R Yr Regn: 10, 17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato K3 c.c. 1591Colour: White A/C: Insured / Std / NI / NASp. Reading: 142695 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAP 8411M3 5749411

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 215/458R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Tourador

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 5/4/23 D.O.I. 6/4/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S R

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 WKsp Paid 1.B.I.

10/5 11Pm @ 25501 Cash (Red. \$3644.80, 59%)

MN: \$62k - LTA: \$30153 - NV: \$31847

Date/Time, File Pass to?

☐ : Prell. Report

1) 15/5/23

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 4Resurvey No. of Trip: 3

Survey Fee:

Transportation

S - RS. \$

Fees

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	514E
Vehicle Details	
Vehicle No.:	SCW382R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 Apr 2023
Vehicle Make:	KIA
Vehicle Model:	CERATO K3 1.6A SUNROOF
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	G4FGHH684121
Chassis No.:	KNAFZ411MJ5749411
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$15,829.00
Original Registration Date:	31 Oct 2017
First Registration Date:	31 Oct 2017
Transfer Count:	2
Actual ARF Paid:	\$15,829.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2027
PARF Rebate Amount:	\$11,080.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,761.00
COE Rebate Amount:	\$19,073.00
Total Rebate Amount:	\$30,153.00

The information contained herein is correct as at 05 Apr 2023

OK

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SG6318H

OUR REF.: SCW382R


TO: FIRST CAPITAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

ESTIMATE FOR VEHICLE NO.: SCW382R

*Not Notarised
21 Apr & 2550/r
Recovery After Paint
9 day,*



DATE: 11/5/2020
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: KIA CERATO K3 1.6A SUNROOF
CHASSIS NO.: KNAFZ411MJ5749411
ENGINE NO.: G4FGHH684121
YEAR MADE: 2017
ACCIDENT DATE: 5 April 2023

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	FRONT FENDER LH		1	\$ 342.00 ✓
2	FRONT FENDER INNER SHIELD LH		1	\$ 86.00 X
3	FRONT FENDER INNER SHIELD CLIP		1	\$ 50.00 X
4	SIDE MIRROR LH		1	\$ 449.00 ✓
7	FRONT KNUCKLE ARM LH		1	\$ 316.00 2
8	FRONT WHEEL HUB LH		1	\$ 135.00 2
9	FRONT WHEEL BEARING LH		1	\$ 118.00 ✓
10	FRONT WHEEL SPORT RIM LH 833		1	\$ 982.00 ✓
11	FRONT STABILIZER BAR		1	\$ 229.00 X
12	FRONT SHOCK ABSORBER LH		1	\$ 283.00 2
13	FRONT TIE ROD LH		1	\$ 102.00 X
14	FRONT TIE ROD END LH		1	\$ 80.00 X
TOTAL:				\$ 3,172.00
LESS 10%:				\$ (317.20)
PARTS TOTAL:				\$ 2,854.80
	SPECIAL NETT			
	BRAKE FLUID		1	\$ 50.00 X
	LABOUR			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS			\$ 1,600.00
	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT			\$ 160.00
	TO REMOVE & REFIT FRONT LH UNDERCARRIAGE			\$ 200.00
	TO REMOVE & REFIT ALL SENSOR			\$ 80.00 X
	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)			\$ 250.00 7
	TO SPRAY PAINT ON THE AFFECTED AREAS			\$ 1,000.00
TOTAL:				\$ 6,194.80
7% GST:				\$ 433.64
GRAND TOTAL:				\$ 6,628.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: