



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23003597/Kwy3e2 Date: 28/04/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBV 1899C	Veh. Inspected	SLA 673K
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS23/1130	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	06/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ESTIMA (A)	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	ACR507014638	Colour	METALLIC GOLD
	Odometer	242300 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	FALKEN	8 mm
	L/H Front Tyre	215/55 R17	FALKEN	8 mm
	R/H Rear Tyre	215/55 R17	FALKEN	8 mm
	L/H Rear Tyre	215/55 R17	FALKEN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/04/2023	Inspection Date	06/04/2023
	Survey held at	RIVERVIEW AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #04-07 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)REGISTRATION DATE: 22 NOV 2006 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	