

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel: 6481 2025 / 6481 5797 Fax: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum Repair
Less 20%SLA673K
parts

Toyota Estima 2.4

List Price
Toyota Less 25%

Rs 1785.80 ✓

Rs 68 ✓

Rs 88 —

Rs 80 —

Rs 296.90 X

Rs 378.90 ✓

Rs 576.90 X

Rs 70 X

Rs 525 X

Rs 550.80 X

Rs 122.80 ✓

Rs 1041.70 —

Rear Bumper

Rear Bumper reflectors x 2pc @ 77 X 2pc = 154 Rs X

Rear Bumper side retainer (outer) x 2pc @ 55.20 x 2pc ^{dismt} = 110.40 X

Rear Bumper side retainer (inner) x 2pc @ 48.30 x 2pc = 96.60 X

Rs 252 X

Boot weatherstrip

Rs 272.60 ✓

Rear end panel top garnish

Rs 60 X

end panel lock catch

Rs 625.50 ✓

Rear end panel

Rs 345 X

Lock Actuator electrical Key

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized

C/Rep &

Money After Paint
6 days

Pg 1

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel: 6481 2025 / 6481 5797 Fax: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum Repair
less 20%

SLA673K

Toyota Estima 2.4

special nett items

nett Price \$

Tailgate inner trim board clips (1set)	nm 50 X
Rear Bumper clips (1set)	nm 45 ✓
Tailgate Reverse Camera	nm 480 X
Reverse parking sensors	shot 250 200nm
Rear end panel for garnish clips (1set)	nm 45 ✓
Rear License plate with holder	nm 50 45nm
Rear windscreen sealant	nm 80 40nm
Rear end panel sealant	nm 80 30nm

Labour charges \$

600

1) To Renew damaged parts, To cut & weld Rear end panel and to repair the accident Area. \$1500

2) To Remove & Refit Rear windscreen 1200 \$200

3) To Renew Tailgate Reverse Camera and Reverse parking sensors, To assemble wiring and check for proper functions. 800 \$120

4) To spray paint Tailgate, Rear Bumper, rear end panel and spare tyre panel. 6600 \$1200

5) To carry out anti-rust treatment at the 6 panels of the accident area. 600 \$120

Pa)