

Section A - Accident Details

Registration Number	SHB5718A
Case Reference Number	TAX/04/23/2011
Registration Date	1/12/20
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	KELVIN LIONG KIN CHUNG (KELVIN LIANG JIANCONG)
Type of Accident	Head To Side
Accident Date and Time	5/4/23 5:10 PM
Accident Reported Date and Time	6/4/23 9:37 AM
Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118104
Special Instruction to ARC, if any	DAMAGE TO THE FRONT LHS & LHS SIDE MIRROR TOWED IN - HEAD TO SIDE
Prepared Date and Time	6/4/23 10:53 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,690.00	\$0.00
Total Spray Cost	\$2,234.00	\$0.00
Total Spare Part Cost	\$12,708.29	\$0.00
Total Other Cost	\$1,541.32	\$0.00
TOTAL COST	\$18,173.61	\$0.00
Jump Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	4 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	06/04/2023 11:26 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Date Generated : 06/04/2023

User ID : munsan

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR FRONT LH PORTION	\$1,690.00	500L
Total Labour	\$1,690.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT BUMPER	\$378.00	200L
O RESPRAY FRONT FENDER LH	\$378.00	200L
O RESPRAY FRONT DOOR LH	\$378.00	200L
O RESPRAY VIEW MIRROR	\$220.00	60L
O RESPRAY ROCKER PANEL MOULDING	\$220.00	150L
RESPRAY WHEEL CAP	\$220.00	X
O RESPRAY RIM	\$220.00	X
O RESPRAY APRON PANEL LH	\$220.00	7
Total Spray Painting & Panel Beating	\$2,234.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
OWING CHARGE	\$56.00	
O WASH AND VACUUM	\$60.00	X
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00	20L
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	30L
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	20L
O TRANSFER DOOR MECHANISM	\$120.00	X
O PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$445.32	nn ✓
O REMOVE AND REFIT TYRE	\$120.00	20L
O REMOVE AND REFIX UNDERCARRIAGE	\$300.00	7
O REPLACE SUNDRY PARTS	\$100.00	nn X
Total Other Costs	\$1,541.32	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	X
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	X
		75310-33050	EMBLEM ASSY FRONT	1.00	\$114.30	25.00	\$85.73	Replace	X
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	X
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	1.00	\$103.70	25.00	\$77.78	Replace	X
		81185-47890	UNIT, HEADLAMP, LH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	X
		53857-12010	RETAINER, FR WHEEL RH	1.00	\$3.50	25.00	\$2.63	Replace	X
		53828-47070	PROTECTOR, FR FENDER LH	1.00	\$101.80	25.00	\$76.35	Replace	7
		53852-47041	PAD, FR WHEEL LH	1.00	\$65.00	25.00	\$48.75	Replace	7
		42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	25.00	\$1,527.23	Replace	✓
		53702-47101	APRON SUB-ASSY, FRONT FENDER, LH	1.00	\$1,060.90	25.00	\$795.68	Replace	✓
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$171.75	Replace	✓
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	7

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 68662623
 Accident Reporting Number : 68662672

Date Generated : 06/04/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	25.00	\$541.58	Replace	7
		48069-47060	LOWER ARM SUB-ASSY, FRONT LH	1.00	\$823.20	25.00	\$617.40	Replace	7
		48520-80639	ABSORBER SET, SHOCK, FRONT LH	1.00	\$511.40	25.00	\$383.55	Replace	7
		87940-47440	MIRROR ASSY, OUTER REAR VIEW, LH	1.00	\$1,454.40	10.00	\$1,308.96	Replace	CM ✓
		87945-47060-A1	COVER, OUTER MIRROR, LH	1.00	\$117.80	25.00	\$88.35	Replace	MT ✓
		75860-47900	MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$649.10	25.00	\$486.83	Replace	7
		67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	R X
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	R ✓
		68740-12120	HINGE LOWER LHF, DOOR	1.00	\$120.00	25.00	\$90.00	Replace	R X
		68720-12151	HINGE ASSY, FRONT DOOR, UPPER LH	1.00	\$105.50	25.00	\$79.13	Replace	R X
		69410-20110	DOOR LOCK STRIKER	1.00	\$42.60	25.00	\$31.95	Replace	R X
		69040-47100	LOCK ASSY, FRONT DOOR LH	1.00	\$607.90	10.00	\$547.11	Replace	R X
		67862-47060	WEATHERSTRIP, FRONT DOOR LH	1.00	\$250.70	25.00	\$188.02	Replace	R X
		68610-47040	CHECK ASSY, FRONT DOOR	1.00	\$199.40	25.00	\$149.55	Replace	R X
		51444-12080	COVER, ENGINE UNDER SIDE LH	1.00	\$86.20	25.00	\$64.65	Replace	7
		53802-47100	FENDER SUB-ASSY, FR, LH	1.00	\$1,060.70	25.00	\$795.53	Replace	MT ✓
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	R ✓
		53876-47060	LINER, FR FENDER, LH	1.00	\$227.80	25.00	\$170.85	Replace	MT ✓
al					\$15,855.94		\$12,708.29		

ded Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
al									