

Section A - Accident Details

Registration Number	SHB5718A
Case Reference Number	TAX/04/23/2011
Registration Date	1/Dec/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	KELVIN LIONG KIN CHUNG (KELVIN LIANG JIANCONG)
Type of Accident	Head To Side
Accident Date and Time	5/Apr/2023 5:10 PM
Accident Reported Date and Time	6/Apr/2023 9:37 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118104
Special Instruction to ARC, if any	DAMAGE TO THE FRONT LHS & LHS SIDE MIRROR TOWED IN - HEAD TO SIDE
Prepared Date and Time	6/Apr/2023 10:53 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,690.00	\$500.00
Total Spray Cost	\$2,234.00	\$810.00
Total Spare Part Cost	\$12,708.29	\$4,167.00
Total Other Cost	\$1,541.32	\$535.32
TOTAL COST	\$18,173.61	\$6,012.32 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	4.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / AIG
ARC / Surveyor Sign Off Date	06/04/2023 2:29 PM	06/04/2023 2:26 PM
Signature		
Remarks	PART BY PART REPAIR/ AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2304-0258	Invoice Number	
Quotation Date	24.04.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,690.00	\$500.00
Total Labour	\$1,690.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$220.00	\$60.00
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	\$150.00
RESPRAY WHEEL CAP	\$220.00	\$0.00
TO RESPRAY RIM	\$220.00	\$0.00
TO RESPRAY APRON PANEL LH	\$220.00	\$0.00
Total Spray Painting & Panel Beating	\$2,234.00	\$810.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$445.32	\$445.32
TO REMOVE AND REFIT TYRE	\$120.00	\$20.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$300.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,541.32	\$535.32

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	100.00	\$0.00	Replace	Repair
		52116-47050	SUPPORT, FR BUMPER LH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given
		75310-33050	EMBLEM ASSY FRONT	0.00	\$114.30	0.00	\$0.00	Replace	Not Given

R
X
X
X } nn

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/05/2023

User ID : PohSuan

		52161-16010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	0.00	\$103.70	0.00	\$0.00	Replace	Not Given	X } nn
		81185-47890	UNIT , HEADLAMP , LH	0.00	\$2,852.40	0.00	\$0.00	Replace	Not Given	X } nn
		51444-12080	COVER, ENGINE UNDER SIDE LH	0.00	\$86.20	0.00	\$0.00	Replace	Check	X
		53802-47100	FENDER SUB-ASSY, FR , LH	1.00	\$1,060.70	25.00	\$795.53	Replace	Replace	√ bt
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√ nec
		53876-47060	LINER, FR FENDER, LH	1.00	\$227.80	25.00	\$170.85	Replace	Replace	√ dis
		53857-12010	RETAINER, FR WHEEL RH	0.00	\$3.50	0.00	\$0.00	Replace	Not Given	X
		53828-47070	PROTECTOR, FR FENDER LH	0.00	\$101.80	0.00	\$0.00	Replace	Check	X } nn
		53852-47041	PAD, FR WHEEL LH	0.00	\$65.00	0.00	\$0.00	Replace	Check	X
		42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	25.00	\$1,527.23	Replace	Replace	√ dd
		53702-47101	APRON SUB-ASSY, FRONT FENDER , LH	1.00	\$1,060.90	25.00	\$0.00	Replace	Not Given	X nn
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$171.75	Replace	Replace	√ cra
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Check	X
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Check	X } nn
		48069-47060	LOWER ARM SUB-ASSY, FRONT LH	0.00	\$823.20	0.00	\$0.00	Replace	Check	X } nn
		48520-80639	ABSORBER SET, SHOCK, FRONT LH	0.00	\$511.40	0.00	\$0.00	Replace	Check	X
		87940-47440	MIRROR ASSY, OUTER REAR VIEW , LH	1.00	\$1,454.40	10.00	\$1,308.96	Replace	Replace	√ cra
		87945-47060-A1	COVER, OUTER MIRROR, LH	1.00	\$117.80	25.00	\$88.35	Replace	Replace	√ mis
		75860-47900	MOULDING ASSY, BODY ROCKER PANEL , LH	0.00	\$649.10	0.00	\$0.00	Replace	Check	X nn
		67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	100.00	\$0.00	Replace	Repair	R
		68610-47040	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X } nn
		67862-47060	WEATHERSTRIP, FRONT DOOR LH	0.00	\$250.70	0.00	\$0.00	Replace	Not Given	X } nn
		69040-47100	LOCK ASSY, FRONT DOOR LH	1.00	\$607.90	100.00	\$0.00	Replace	Repair	R
		69410-20110	DOOR LOCK STRIKER	0.00	\$42.60	0.00	\$0.00	Replace	Not Given	X nn
		68720-12151	HINGE ASSY, FRONT DOOR , UPPER LH	1.00	\$105.50	100.00	\$0.00	Replace	Repair	R
		68740-12120	HINGE LOWER LHF, DOOR	1.00	\$120.00	100.00	\$0.00	Replace	Repair	R
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√ nec
Total					\$15,855.94		\$4,167.00			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

4,167.00
 + 500.00
 + 1345.32
 6,012.32