

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) - Fax: 64514658
GST Reg No. 201629438M

02/04/2023

Owner: TAN YONG HENG

ESTIMATE TO REPAIR HONDA SHUTTLE HYBRID - SML6902R

1pc	rear tailgate "HYBRID" emblem	ms 85.20	—
1pc	rear tailgate "SHUTTLE" emblem	sm 85.20	—
1pc	rear bumper	\$ 1,150.60	?
2pcs	rear bumper side retainer @\$46.50	sh 93.00	X
1pc	rear end panel	sl 601.50	X
1pc	rear end panel sensor	\$ 190.50	?
1pc	rear end panel inner garnish	\$ 195.55	?
		\$ 2,401.55	
less 20%		\$ 480.31	
		\$ 1,921.24	

1set rear parking sensor s.nett sm 280.00 X

spray painting	\$ 800.00	400
labour charges	\$ 800.00	400
Total	\$ 3,801.24	

Not Authorized
L/R &
Penny After Paint
3days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: