

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA9571J

30.03.2023

MAKE REG.30.04.2019

CHIANG/INCOME L/S

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER / CRP		\$459.40
1	REAR BUMPER SIDE BRACKET RH ?XSVC		\$55.80
1	REAR BUMPER CENTRE MOULDING / DEF		\$451.25
1	REAR BUMPER REINFORCE MENT ?XSVC		\$394.80
1	REAR BUMPER REINFORCEMENT STAY LH ?XSVC		\$138.10
1	REAR BUMPER TOW COVER XSVC		\$98.80
10	REAR BUMPER CLIPS / NBL		\$22.00
	SUB TOTAL		\$1,620.15
	20.00%		\$324.03
	DISCOUNTED TOTAL		\$1,296.12
1	REAR BUMPER MAT / NBL		\$50.00
1	REAR NUMBER PLATE W/HOLDER / HOLDER ONLY. NO PLATE SVC def		30 \$55.00
1	REAR REVERSE SENSOR XSVC		\$180.00
			\$261.50
	Labour Charge		
	Panel Beating		3.50 \$600.00
	Spray Painting Charge		2.50 \$300.00
	Check Lighting / Wiring.		NN X \$60.00
	Remove/refix Reverse sensor		30 \$60.00
	TOTAL LABOUR		\$1,020.00
	ESTIMATE TOTAL		\$2,577.62
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

N#2 CLK

5/4/2023 1618

LIS

2 Days

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No iller modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: