



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79, ROBINSON ROAD #09-01
SINGAPORE 068897

ESTIMATE

NO : QUOT202303-000040(00)
DATE : 06/04/2023
POLICY NO : SP2003902365
VEH REG NO : GBM1749A
MAKE/MODEL : MERCEDES BENZ EVITO 112
LONG AT
CHASSIS NO : W1V44760324162801
ENGINE NO :
REG. DATE : 2022

ATTN : MOTOR CLAIMS DEPT
TEL : FAX :

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 01/03/2023

*Not Authorized
Repairing After Repairing
3 days
Ex TBA*

Estimate Repair Cost to Vehicle No : GBM1749A

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy - LH	1	580.00	580.00 X
2 Front bumper	1	1,880.00	1,880.00 ✓
3 Front bumper reinforcement	1	620.00	620.00 X
4 Front bumper side retainer - LH	1	58.00	58.00 X
5 Front bumper holder - LH	1	58.00	58.00 X
6 Front bumper electric charger inner cover	1	78.00	78.00 ✓
7 Front bumper electric charger outer cover	1	60.00	60.00 ✓
8 Front bumper charger cover push button switch	1	98.00	98.00 ✓
9 Front bumper charger push button actuator	1	85.00	85.00 ?
10 Front bumper socket access	1	215.00	215.00 ?
11 Front bumper electrical wiring harness	1	1,950.00	1,950.00 X
12 Front bumper clips	15	5.50	82.50 ✓
			5,202.50
		Add 10%	1,138.45
			6,340.95
LABOUR			
13 To panel beat and straighten LH front fender, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00 200
14 To putty and spray paint on affected areas	1	800.00	800.00 250
15 To reset & reprogram electric charger wiring system (online)	1	350.00	350.00 ?
			1,950.00

TOTAL S\$ 8,290.95

ADD GST @ 8% 663.28

GRAND TOTAL S\$ 8,954.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE DOLLAR EIGHT THOUSAND NINE HUNDRED FIFTY-FOUR AND CENTS TWENTY-THREE ONLY