

ASS. REC. BY:

REF:

SMR/ 23003613/k nys

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1-B-1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

/

Unable to check YOR.

14/6

/ Rmp

810501

Cen

(Red. & 2395.50, 697.)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

: Parking

: Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Veh No:

GBF 9905A

Yr Regn:

051 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS

NV350

c.c

2488

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

139638

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JNIMC 2482880007592

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

195R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dunlop

Front

R/Bal.

6

mm

Rear

R/Bal.

2

mm

L/Bal.

62

mm

L/Bal.

2

mm

D.O.A.

22/3/23

D.O.I.

16/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP(MSFC)Vehicle No. : GBF9055AMake & Model : NISSAN NV350

Year of Manufacture : _____

Chassis No. : JN1MC2E26Z0007592Ins Company : GE

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 22.03.23

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair EstimatesCase Owner : KELVIN

Signature : _____

Parts (a) Cost / List Price Items \$ 2,865.00Plus/Less 30% \$ 859.50Total of Cost / List \$ 2,005.50

(b) Nett Price Items _____

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 580.00Total Parts Cost (Appendix A) \$ 2,585.50Labour (Appendix B) \$ 860.00Total Repair Cost \$ 3,445.50**Operation**

KELVIN SU TEL:97864236 E:kelvinsukwen@cdge.com.sg

JOHARI TEL:97213705 E:joharibh@sparkcarcare.com

OI SUN PIN TEL: 97288916 E: oisunpin@cdge.com.sg

SOO LEONG KEAT TEL:98328740 E:soolk@cdge.com.sg

*Not Authorized
Resurvey After Repair*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : KennethCompany : CDGSurvey conducted on : 11/4/23 at _____**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : LeDate: 11/4/23

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : GBF9055A Case Owner : KELVIN

Make & Model : NISSAN NV350 Year Manufacture : 0

Chassis No : JN1MC2E26Z0007592 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : KELVIN Type of Claim : TP(MSFC)

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1	R	\$ 550.00			X
2	REAR BUMPER CLIPS	10	NA	\$ 35.00			X
3	REAR BUMPER BRACKET	1	SN	\$ 65.00			X
4	RHR FENDER	1	R	\$ 1,900.00			X
5	RHR TAILLAMP	1	RU	\$ 235.00			✓
6	TAILLAMP CLIPS	2	RU	\$ 15.00			✓
7	FUEL TANK CAP	1	RU	\$ 65.00			X
8	ARTWORK	1		(Bill)	RU	\$ 580.00	✓ B.71
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No. : **GBF9055A**

Case Owner	:	KELVIN
------------	---	--------

Make & Model : **NISSAN NV350**

Year of Manufacture	:	0
---------------------	---	---

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.