

ASS. REC. BY:

REF:

AIG/ 23 003623/1cp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1-B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SBM 9J

Yr Regn:

02, 23

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tesla Model Y

c.c.

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

3485

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LRWYHCF83NC574925

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

255/45R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

1 tank code

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

1/4/23

D.O.I.

5/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/5 @ 3434.50 Car

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Date: 4/4/2023
Vehicle No: SBM9J
Model: TESLA MODEL Y RWD
Chassis: LRWYHCFS3NC574925
Reg.Year: 2022

Not Notion
Penny B4 pain
4 days

Third Party Insurer: AIG
Third Party Veh No: SKR3900H
Date of Accident: 1/4/2023
Estimator: Simon Koh
Surveyor: *LKK Kenneth*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR LOWER BUMPER COVER	1	\$ 542.06	\$ <i>711</i> 542.06
2	REAR BUMPER COVER	1	\$ 836.45	\$ <i>1040</i> 836.45
3	TOW HITCH COVER	1	\$ 20.56	\$ <i>26</i> 20.56
4	REAR LIFTGATE ASSY	1	\$ 1,219.63	\$ <i>1544</i> 1,219.63
			PARTS TOTAL	\$ 2,618.70

Rear bumper reflector cm 40.19

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSHIELD SEALANT	1	\$ 80.00	\$ <i>100</i> 80.00
			S/N TOTAL	\$ 80.00

LABOUR CHARGES:

LABOUR TO REMOVE, REPLACE/REPAIR, REALIGN AND REFIX THE LISTED ACCIDENT AFFECTED DAMAGED PARTS \$ 600.00 *400*

LABOUR TO REMOVE, TRANSFER & REFIX REAR TAILGATE INNER MECHANISM & TRIM BOARD FROM AFFECTED TAILGATE TO NEW TAILGATE \$ 120.00 *60*

LABOUR TO REMOVE AND REPLACE/REFIX REAR WINDSHIELD & MOULDING. TO PERFORM WATER LEAK TEST \$ 150.00 *120*

LABOUR TO PUTTY, RESPRAY AND POLISH REAR TAILGATE, REAR BUMPER AND OTHER ACCIDENT AFFECTED AREA \$ 600.00 *440*

TO TUFF KOTE AND UNDERSEAL MATERIALS \$ *120* 120.00 *X*

LABOUR TOTAL \$ 1,590.00

TOTAL \$ 4,288.70

Simon

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Head office

8 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500 Tel: (+65) 6484 0619 Fax: (+65) 6481 1903
Bik 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047 Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

