

Date: 4/4/2023

Vehicle No: SBM9J

Model: TESLA MODEL Y RWD

Chassis: LRWYHCFS3NC574925

Reg. Year: 2022

Third Party Insurer: AIG

Third Party Veh No: SKR3900H

Date of Accident: 1/4/2023

Estimator: Simon Koh

Surveyor: LKK Kenneth

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR LOWER BUMPER COVER	1	\$ 542.06	\$ 542.06
2	REAR BUMPER COVER	1	\$ 836.45	\$ 836.45
3	TOW HITCH COVER	1	\$ 20.56	\$ 20.56
4	REAR LIFTGATE ASSY	1	\$ 1,219.63	\$ 1,219.63
			PARTS TOTAL	\$ 2,618.70

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSHIELD SEALANT	1	\$ 80.00	\$ 80.00
			S/N TOTAL	\$ 80.00

LABOUR CHARGES:

LABOUR TO REMOVE, REPLACE/REPAIR, REALIGN AND REFIX THE LISTED ACCIDENT AFFECTED DAMAGED PARTS \$ 600.00

LABOUR TO REMOVE, TRANSFER & REFIX REAR TAILGATE INNER MECHANISM & TRIM BOARD FROM AFFECTED TAILGATE TO NEW TAILGATE \$ 120.00

LABOUR TO REMOVE AND REPLACE/REFIX REAR WINDSHIELD & MOULDING. TO PERFORM WATER LEAK TEST \$ 150.00

LABOUR TO PUTTY, RESPRAY AND POLISH REAR TAILGATE, REAR BUMPER AND OTHER ACCIDENT AFFECTED AREA \$ 600.00

TO TUFF KOTE AND UNDERSEAL MATERIALS \$ 120.00

LABOUR TOTAL \$ 1,590.00

TOTAL \$ 4,288.70

Simon

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: 4/4/2023

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9839 Fax: (+65) 6484 1011

TM