



Section A - Accident Details

Registration Number	SHF282B
Case Reference Number	TAX/03/23/2079
Registration Date	1/Nov/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LOO TOON KEONG (LU DUNQIANG)
Type of Accident	Head to Rear
Accident Date and Time	31/Mar/2023 5:30 PM
Accident Reported Date and Time	1/Apr/2023 8:49 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118086
Special Instruction to ARC, if any	DAMAGE TO REAR RIGHT OF MY TAXI
Prepared Date and Time	3/Apr/2023 3:28 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$200.00
Total Spray Cost	\$1,296.00	\$320.00
Total Spare Part Cost	\$4,500.26	\$1,074.57
Total Other Cost	\$500.00	\$65.00
TOTAL COST	\$7,141.26	\$1,659.57
Lump Sum Total	\$7,150.00	\$1,650.00
Number of Repair Days	7.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / III
ARC / Surveyor Sign Off Date	10/04/2023 5:09 PM	10/04/2023 5:00 PM
Signature		
Remarks	INITIAL = 7 DAYS WITH SUPPLEMENTARY = 0 DAY TOTAL = 7 DAYS	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2304-0260	Invoice Number	
Quotation Date	24.04.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$845.00	\$200.00
Total Labour	\$845.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$120.00
Total Spray Painting & Panel Beating	\$1,296.00	\$320.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$15.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$50.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$500.00	\$65.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.18	Replace	Replace
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check
		5246247030	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5246247020	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5246247010	PAD, RR BUMPER, RH & LH , 3	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	Replace
		5219147030	SEAL, RR BUMPER ARM, RH & LH	1.00	\$12.30	25.00	\$9.23	Replace	Replace
		5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Check
		5259147050	SEAL, RR BUMPER , RH	0.00	\$95.50	0.00	\$0.00	Replace	Check

√ br
X
√ } nec
√ } nec
√ } nec
√ } nec
√ } nec
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 02/05/2023

User ID : PohSuan

		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√	nec
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	Replace	√	cra
		52565479 00	FILLER, RR BUMPER , RH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X	
		52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$16.70	0.00	\$0.00	Replace	Not Given	X	
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	
		89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	X	
		90189060 29	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X	
		81551472 81	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X	
		81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X	
		58398470 50	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X	
		66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	X	
		67005474 40	TAIL GATE PANEL SUB- ASSY, BACK DOOR	0.00	\$1,238.40	0.00	\$0.00	Replace	Not Given	X	
		76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$992.30	0.00	\$0.00	Replace	Not Given	X	
		75441470 90	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√	
		75442471 30	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√	} nec
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√	
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√	} nec
		75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$77.40	25.00	\$58.05	Replace	Replace	√	
		58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given	X	
Total					\$6,802.70		\$1,073.13				

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	Replace
Total					360.10		270.08		

	1,343.21	
	-20%	
	1074.57	L/S \$1,650/-
+	200.00	
+	385.00	
	1,659.57	