Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Irene Tay Hui Ping 28 Apr 2023 Date:

Preliminary Advice

Vehicle No : SMX6887M **Accident Date** : 27/03/2023

: OPEL GRANDLAND X Policy No. Make

DMHCSNW00000932300

Assignment Date : 06/04/2023 Excess : S\$1.250.00

: 27/04/2023 Date of Inspection Est. Duration of Repair : 5

: FIRST AUTOWORKS PTE LTD (HQ) Inspection At

23 KAKI BUKIT AVE 4 #04-01 SOUTH WING

SINGAPORE 415933

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,849.10
Revised Amount	:S\$	8,091.00
Check Items (Estimated)	:S\$	7,022.50
Total	:S\$	15,113.50

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$

Pre-Accident Value :S\$ 88,000.00 COE / PARF Rebate :S\$ 37,428.00 Salvage Value :S\$

Margin for Repair :S\$ 50,572.00

Remarks

(X)	The vehicle is repairable at our adjusted amour	it. We have also	confirmed excess	s and policy coveraເ	ge. Kindly
	let us have your authorisation.				

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to part prices and labour cost check.