

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

GD12386580 DATE : 06.04.2023

TO : ALLIANZ MOTOR CLAIMS DEPTS
VEHICLE NO : SGT2302C
MODEL : HONDA FIT
DATE OF ACCIDENT : 05.04.2023
TIME OF ACCIDENT : 17:45 HOURS

Ezlyn.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 490.00	\$ 490.00
2	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 35.20	\$ 70.40
3	TAIL GATE <i>Distorted</i>	1	\$ 849.90	\$ 849.90
4	TAIL GATE OUTER HANDLE <i>Cracked</i>	1	\$ 164.90	\$ 164.90
5	TAIL GATE LOGO <i>new</i>	1	\$ 24.70	\$ 24.70
6	TAIL GATE EMBLEM "FIT" <i>new</i>	1	\$ 28.80	\$ 28.80
7	TAIL GATE WINDSCREEN MOULDING <i>new</i>	2	\$ 76.00	\$ 152.00
8	TAIL GATE WIPER ARM <i>new</i>	1	\$ 125.30	\$ 125.30
9	TAIL GATE WIPER ARM BOLT COVER <i>new</i>	1	\$ 42.10	\$ 42.10
10	TAIL GATE WIPER MOTOR <i>new</i>	1	\$ 436.30	\$ 436.30
11	TAIL GATE NUMBER PLATE LAMP <i>new</i>	2	\$ 45.00	\$ 90.00
12	TAIL GATE DAMPER <i>new</i>	2	\$ 194.40	\$ 388.80
13	TAIL GATE HINGE <i>new</i>	2	\$ 42.00	\$ 84.00
14	TAIL GATE INNER HOLDER <i>Missing</i>	1	\$ 47.10	\$ 47.10
15	TAIL GATE STOPPER <i>new</i>	2	\$ 12.00	\$ 24.00
16	TAIL GATE INNER LOCK <i>Distorted</i>	1	\$ 169.40	\$ 169.40
17	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 25.00	\$ 25.00
18	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 134.50	\$ 134.50
19	TAIL GATE INNER TRIM <i>Cracked</i>	1	\$ 372.20	\$ 372.20
20	TAIL GATE WIRE HARNESS <i>new</i>	1	\$ 899.60	\$ 899.60

265

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGT2302C**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 05.04.2023
 TIME OF ACCIDENT : 17:45 HOURS

21	TAIL LAMP <i>Culled</i>	2	\$	296.10	\$	592.20	✓
22	TAIL LAMP PANEL (OUTER) <i>Deled</i>	2	\$	168.30	\$	336.60	✓
23	TAIL LAMP INNER PANEL (UPPER) <i>3 Regis</i>	2	\$	296.60	\$	593.20	✓
24	TAIL LAMP INNER PANEL (LOWER) <i>3 Regis</i>	2	\$	284.70	\$	569.40	✓
25	REAR FENDER INNER TRIM <i>Deled</i>	2	\$	298.90	\$	597.80	✓
26	REAR END PANEL <i>Deled</i>	1	\$	356.70	\$	356.70	✓
27	REAR END PANEL TOP GARNISH <i>Deled</i>	1	\$	116.20	\$	116.20	✓
28	REAR FLOOR PANEL <i>Buckled</i>	1	\$	1,147.70	\$	1,147.70	735
29	REAR FLOOR PANEL BOTTOM CROSS MEMBER <i>Regis</i>	1	\$	867.30	\$	867.30	+
30	REAR FLOOR PANEL TOP BOARD <i>Deled</i>	1	\$	185.60	\$	185.60	+
31	REAR CHASSIS MEMBER RH <i>Regis</i>	1	\$	798.80	\$	798.80	+
32	REAR CHASSIS TOP PANEL <i>3 Regis</i>	2	\$	196.10	\$	392.20	+
33	REAR TOWING HOOK PANEL <i>3 Regis</i>	1	\$	323.20	\$	323.20	+
34	CENTER EXHAUST <i>3 Best</i>	1	\$	769.30	\$	769.30	+
35	CENTER EXHAUST INSULATOR <i>3 New</i>	1	\$	49.80	\$	49.80	+
36	CENTER EXHAUST GASKET (SET) <i>3 New</i>	1	\$	60.00	\$	60.00	32
37	REAR EXHAUST PIPE <i>3 Best</i>	1	\$	688.70	\$	688.70	✓
38	REAR EXHAUST INSULATOR <i>3 New</i>	1	\$	58.40	\$	58.40	+
39	REAR EXHAUST GASKET (SET) <i>3 New</i>	1	\$	60.00	\$	60.00	35
40	REAR EXHAUST MOUNTING <i>3 New</i>	4	\$	35.00	\$	140.00	+
41	REAR SPARE TYRE BOLT <i>3 New</i>	1	\$	121.00	\$	121.00	+

7338.10
 5870.48

TOTAL PRICE \$ 13,443.10
 LESS 20% \$ 2,688.62
SUB TOTAL PRICE \$ 10,754.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
3	TAIL GATE WINDSCEEN SEALANT <i>3</i>	1	\$ 80.00	\$ 80.00
4	TAIL GATE WINDSCEEN INNER SEAL <i>New</i>	1	\$ 60.00	\$ 60.00
5	TAIL AGTE WINDSCREEN SOLAR FILM <i>3</i>	1	\$ 150.00	\$ 150.00
6	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00
7	TAIL LAMP PANEL (OUTER) SEALANT <i>New</i>	2	\$ 80.00	\$ 160.00

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGT2302C**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 05.04.2023
 TIME OF ACCIDENT : 17:45 HOURS

8	REAR FENDER INNER TRIM CLIPS (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00 <i>60.</i>
9	REAR END PANEL INSULATION SEAL <i>Neu</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
10	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00 <i>10.</i>
11	REAR FLOOR PANEL INSULATION SEAL <i>Neu</i>	1	\$ 350.00	\$ 350.00 <i>150</i>
12	REAR CHASSIS TOP PANEL SEALANT <i>Neu</i>	1	\$ 150.00	\$ 150.00 <i>t.</i>
13	REVERSE SENSOR <i>Dmgd</i>	1	\$ 220.00	\$ 220.00 <i>200</i>
14	REVERSE CAMERA <i>Dmgd</i>	1	\$ 450.00	\$ 450.00 <i>350</i>

1190

TOTAL \$ 2,050.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,800.00	<i>1300</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	<i>900.</i>
3	TUFF COAT	\$ 250.00	<i>80.</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 550.00	<i>80</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	<i>50</i>
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
9	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>X</i>
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGT2302C**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 05.04.2023
 TIME OF ACCIDENT : 17:45 HOURS

11	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
12	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
13	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 100.00	X
14	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X 120.
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

2860

TOTAL \$ 7,110.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,804.48
 TOTAL LABOUR COST : \$ 7,110.00
 TOTAL REPAIR COST : \$ 19,914.48

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Adrian Lj
 r/s 06/04/23.
 09 Days

Total: 9920.48

r/s: 7.9K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: