



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : SML5642Y

Make & Model : TOYOTA PRIUS

Year of Manufacture : 2019

Chassis No. : JTDKB3FU103081023

Ins Company : LONPAC INSURANCE

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 24/03/2023

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 2,081.20

Plus/Less 25% \$ 520.30

Total of Cost / List \$ 1,560.90

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 50.00

Total Parts Cost (Appendix A) \$ 1,610.90

Labour (Appendix B) \$ 1,050.00

Total Repair Cost \$ 2,660.90

Contact No
Operation
KELVIN SU
TEL: 9786 4236
E: kelvinsukwen@cdge.com.sg

JOHARI
TEL: 972103705
E: joharibh@sparkcarcare.com

SUN PIN
TEL: 9728 8916
E: oisunpin@cdge.com.sg

SOOLEONG KEAT
TEL: 9832 8740
E: soolk@cdge.com.sg

*NOT Authorized
2/ Pay &
Money After Pain*

The above total will be subjected to 8% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 10/4/23 at 11.50am

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 10/4/23

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SML5642Y Case Owner : 0

Make & Model : TOYOTA PRIUS Year Manufacture : 2019

Chassis No : JTDKB3FU103081023 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1	<i>Bur</i>	\$ 531.80			<i>✓</i>
2	REAR BUMPER LOWER GARNISH	1	<i>outlet</i>	\$ 692.30			<i>✓</i>
3	REAR BUMPER TOW COVER	1	<i>rep</i>	\$ 28.50			<i>✓</i>
4	REAR BUMPER LOWER LH GARNISH	1		\$ 148.30			<i>7</i>
5	REAR REINFORCEMENT BAR	1		\$ 399.90			<i>7</i>
6	REVERSE SENSOR	1	<i>in</i>	\$ 280.40			<i>X</i>
7	REAR BUMPER CLIPS	1	<i>in</i>			\$ 50.00	<i>✓</i>
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

