

REF:

From: _____ Date: _____

Veh No: 5ND178J Yr Regn: 2019 / oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: King Stinger C.C. 1998

Colour Blue A/C: Insured / Std / NI / NA

Sp. Reading 43301 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAE351A ML60/4590

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R19.

R: 245/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Front

Rear

R/Bal. 96 mm R/Bal. 96 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 11/04/23

Survey held at Cycle and Carriage' ubi.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

<input type="checkbox"/>	: Site Insp	(\$
<input type="checkbox"/>	: Interview	(\$
<input type="checkbox"/>	: Tech. Invs	(\$
<input type="checkbox"/>		

Survey Fee:

Transportation:

$$S \div RS, \quad S$$

Photos

Others

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
NG WEI HONG BLK 870A TAMPINES STREET 86 #10-14 SINGAPORE 521870 Contact No Mobile: 98388969	<table> <tr> <td>Cust No/Name</td><td>/NG WEI HONG</td></tr> <tr> <td>Reg No/Reg Date</td><td>SND178J*ECB19/ 04/10/201</td></tr> <tr> <td>Date In/Mileage</td><td>04/04/2023/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAE351AML6074590</td></tr> <tr> <td>Engine No</td><td>G4KLKH025470</td></tr> <tr> <td>Make/Model</td><td>KIA/STINGER 2.0 A GAA3 RED LEATHER</td></tr> <tr> <td>Colour/Trim</td><td>M6B MICRO BLUE / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/NG WEI HONG	Reg No/Reg Date	SND178J*ECB19/ 04/10/201	Date In/Mileage	04/04/2023/ 0	Chassis No	KNAE351AML6074590	Engine No	G4KLKH025470	Make/Model	KIA/STINGER 2.0 A GAA3 RED LEATHER	Colour/Trim	M6B MICRO BLUE / WK SATURN BLACK
Cust No/Name	/NG WEI HONG														
Reg No/Reg Date	SND178J*ECB19/ 04/10/201														
Date In/Mileage	04/04/2023/ 0														
Chassis No	KNAE351AML6074590														
Engine No	G4KLKH025470														
Make/Model	KIA/STINGER 2.0 A GAA3 RED LEATHER														
Colour/Trim	M6B MICRO BLUE / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00086	Cash	05/04/2023/ 08:59	REN	979 / Renemer Ramirez Bag	18456			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT								
ACCIDENT ON 04/04/2023 ALONG TAMPINES STREET 11 BLK 139 CARPARK								
OWNER CLAIMING THIRD PARTY								
REQUIRED REPLACEMENT VEHICLE								
TP#: GBL359D TP INS: LONPAC								✓ 280.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK ON KDS AND CLEAR TROUBLE CODE								✓ 80.00
A 90000001								
TO CHECK WIRING AND ELECTRICAL SYSTEM								640 1280.00
E PNT88000								
TO REPLACE RH HEADLAMP, LOGO, FRONT BUMPER, CLIPS, BRACKETS, UPR & LWR								
GRILLE, RH AIR COVER, BUMPER ABSORBER, RH INR AIR DUCT, WASHER TANK, ETC								
STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS								550 1100.00
E PNT98000								
SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS								80 100.00
E PNT88000								
TO CHECK & TEST FRONT PARKING ASSIST								20 50.00
M SUNDRY New								
SUNDRIES								
M	RH LAMP ASSY-HEAD	New			1.00	3977.00	00.00	+ 3977.00
M	LOGO ASSY-KIA SUB	New			1.00	45.00	00.00	✓ 45.00
M	COVER-FR BUMPER	torn			1.00	646.00	00.00	✓ 646.00
M	CLIP-BUMPER	New			10.00	1.00	00.00	✓ 10.00
M	RH SIDE BRACKET-FR BUMPER	NEC			1.00	11.00	00.00	✓ 11.00
M	LH SIDE BRACKET-FR BUMPER	NEC			1.00	11.00	00.00	+ 11.00
M	GRILLE ASSY-RADIATOR	New			1.00	444.00	00.00	+ 444.00
M	LWR GRILLE-FRONT BUMPER	New			1.00	391.00	00.00	+ 391.00
M	RH COVER ASSY-AIR CURTAIN	cracked			1.00	126.00	00.00	- 126.00
M	ABSORBER-FRONT BUMPER ENERGY	New			1.00	105.00	00.00	+ 105.00
M	AIR DUCT-FR BUMPER, RH	2			1.00	24.00	00.00	+ 24.00
M	RESERVOIR & PUMP ASSY-WASHER	New			1.00	294.00	00.00	+ 294.00

Confirm & accepted by

Adrian Lim
 11/04/23.
 03 Days

Nett

8,974.00

8% GST on

8974.00

717.92

Total Payable

9,691.92

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.